

Equipment ID: 12769 VIN: BT069045 Year: 2011 Manufacturer: Hyundai Primary Plate: _____

DOT / BIT Inspection and PM Worksheet

Check Mark = OK

X = Needs Further Attention

R = Repaired

N/A = Not Applicable

☒ Glad Hands & Rubber Grommets	☐ Repaired
☒ 7-Way Electrical Plug	☐ Repaired
☒ Registration, Valid License Plate and sticker	☐ Repaired
☒ Lights, Wiring and Splice Conditions	☐ Repaired
☒ Exterior Trailer - Body Condition and Coupling Device	☐ Repaired
☒ Corner Locking Devices	☐ Repaired
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	☐ Repaired
☒ Fuel Tank and Fuel System (Heater)	☐ Repaired
☒ Air Brake System - Test for leaks	☐ Repaired
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks	☐ Repaired
☒ ABS System - Actuate	☐ Repaired
☒ Air Lines - Check for damage / wear / chaffing	☐ Repaired
☒ Suspension Hangers - Free of defects and cracks	☐ Repaired
☒ Air Tank and Mounting Brackets	☐ Repaired
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	☐ Repaired
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	☐ Repaired
☒ Suspension / U-Bolts / Springs - Free of defects and cracks	☐ Repaired
☒ Flashed Winches - Lubricate and Cycle	☐ Repaired
☒ Sub-Frame - Free of Cracks / Bent Crossmembers	☐ Repaired

☒ Aerodynamic Side Skirts	☐ Repaired
☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	☐ Repaired
☒ Lubricant Level in each Wheel End - Fill if necessary	☐ Repaired
☒ Wheels - Check for Cracks / Tire Matching	☐ Repaired
☒ Tires - free of impermissible damage or wear	☐ Repaired
☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	☐ Repaired
☒ Metal Flow-Thru Valve Stem Caps	☐ Repaired
☒ Conspicuously Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	☐ Repaired
☒ Mudflaps, Brackets, Rubber Deck Bumpers, and Rear Impact Guard	☐ Repaired
☒ Doors - Proper Operation	☐ Repaired
☒ Door Hold Backs and Pull Handles - Present & Functional	☐ Repaired
☒ All Hinges, Rollers, Locks - Lubricate	☐ Repaired
☒ Interior Trailer - Floor, Roof, and Side Walls	☐ Repaired
☒ Interior - Resecure Plywood as Needed	☐ Repaired
☒ DOT Inspected - Sticker Applied	☐ Repaired
☒ California BIT Inspected & Passed	☐ Repaired

NOTES:

TIRES (in 32nds)

Position	TD	Brand	PSI	Position	TD	Brand	PSI
LF Front	12		100	RF Front	10		100
LR Front	10		100	RL Front	2		100
LM Middle				RM Middle			
LO Middle				RO Middle			
LI Rear	9		100	RI Rear	10		100
LI Rear	10		100	RI Rear	4		100

BRACKETS (in 32nds)

Axle	Position	Depth
1	L Front	5/8
2	R Front	5/8
3	L Middle	
	R Middle	
	L Rear	5/8
	R Rear	

Hub: **0477069**

Engine Hrs: _____

Prod. Time: _____

Fuel Gals: _____

By signing and dating this form the Inspector certifies (1) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (2) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By: [Signature]
(Inspector Signature)

Inspection Date: **9.10.16**

Print Name: Reston Althv Company Name: Dedicated Fleet Services, LLC