

Equipment ID: 12960 VIN: CL692396 Year: 2011 Manufacturer: Volvo

DOT / BIT Inspection and PM Worksheet

- Check Mark = OK X = Needs Further Attention
- ☒ Glad Hands & Rubber Grommets Repaired ☐
 - ☒ 7-Way Electrical Plug Repaired ☐
 - ☒ Registration, Valid License Plate and sticker Repaired ☐
 - ☒ Lights, Wiring and Splice Conditions Repaired ☐
 - ☒ Exterior Trailer - Body Condition and Coupling Device Repaired ☐
 - ☒ Corner Locking Devices Repaired ☐
 - ☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle Repaired ☐
 - ☒ Fuel Tank and Fuel System (If/when) Repaired ☐
 - ☒ Air Brake System - Test for leaks Repaired ☐
 - ☒ Dump Valve (Air Ride Only) - Test operation and check for leaks Repaired ☐
 - ☒ ABS System - Actuate Repaired ☐
 - ☒ Air Lines - Check for damage / wear / chaffing Repaired ☐
 - ☒ Suspension Hangers - Free of defects and cracks Repaired ☐
 - ☒ Air Tank and Mounting Brackets Repaired ☐
 - ☒ Brakes - Drums / Linings / Air Chambers - Free of defects and cracks Repaired ☐
 - ☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust Repaired ☐
 - ☒ Suspension / U-Bolts / Springs - Free of defects and cracks Repaired ☐
 - ☒ Flatbed Winches - Lubricate and Cycle Repaired ☐
 - ☒ Sub-Frame - Free of Cracks / Bent Crossmembers Repaired ☐

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	9		100	RO Front	9		100
2	LI Front			100	RI Front			100
3	LO Middle				RO Middle			
4	LI Middle				RI Middle			
5	LO Rear	10		100	RO Rear	9		100
6	LI Rear			100	RI Rear			100

Brakes (in 32nds)

Axle	Position	Depth
1	L Front	5/8
2	R Front	5/8
3	L Middle	5/8
4	R Middle	5/8
5	L Rear	5/8
6	R Rear	5/8

- R = Repaired N/A = Not Applicable
- ☒ Aerodynamic Side Skirts Repaired ☐
 - ☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper Repaired ☐
 - ☒ Lubricant Level in each Wheel End - Fill if necessary Repaired ☐
 - ☒ Wheels - Check for Cracks / T/W Matching Repaired ☐
 - ☒ Tires - Free of impermissible damage or wear Repaired ☐
 - ☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs Repaired ☐
 - ☒ Metal Flow-Thru Valve Stem Caps Repaired ☐
 - ☒ Conspicuously Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards Repaired ☐
 - ☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard Repaired ☐
 - ☒ Doors - Proper Operation Repaired ☐
 - ☒ Door Hold Backs and Pull Handles - Present & Functional Repaired ☐
 - ☒ All Hinges, Rollers, Locks - Lubricate Repaired ☐
 - ☒ Interior Trailer - Floor, roof, and Side Walls Repaired ☐
 - ☒ Interior - Resecure Plywood as Needed Repaired ☐
 - ☒ DOT Inspected - Sticker Applied Repaired ☐
 - ☒ California BIT Inspected & Passed Repaired ☐

NOTES:

By signing and dating this form the Inspector certifies (1) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396.27, and (2) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.27.

Inspection Conducted By: Shawn Todd (Inspector Signature)

Print Name: Shawn Todd Company Name: Dedicated Fleet Services, LLC

Inspection Date: 9-10-26

Hubs: 0

Engine Hrs: _____

Prod. Time: _____

Fuel Gals: _____