

Equipment ID

VIN

Year

Manufacturer

Primary Plate

154077

FT 154077 2014

Hyundai

DOT / BIT Inspection and PM Worksheet

Check Mark = OK

X = Needs Further Attention

R = Repaired

N/A = Not Applicable

☒ Glad Hands & Rubber GrommetsRepaired ☐☒ 7-Way Electrical PlugRepaired ☐☒ Registration, Valid License Plate and stickerRepaired ☐☒ Lights, Wiring and Splice ConditionsRepaired ☐☒ Exterior Trailer - Body Condition and Coupling DeviceRepaired ☐☒ Corner Locking DevicesRepaired ☐☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & CycleRepaired ☐☒ Fuel Tank and Fuel System (Recofer)Repaired ☐☒ Air Brake System - Test for leaksRepaired ☐☒ Dump Valve (Air Ride Only) - Test operation and check for leaksRepaired ☐☒ ABS System - ActuateRepaired ☐☒ Air Lines - Check for damage / wear / chaffingRepaired ☐☒ Suspension Hangers - Free of defects and cracksRepaired ☐☒ Air Tank and Mounting BracketsRepaired ☐☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracksRepaired ☐☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjustRepaired ☐☒ Suspension / U-Bolts / Springs - Free of defects and cracksRepaired ☐☒ Flatbed Winches - Lubricate and CycleRepaired ☐☒ Sub-Frame - Free of Cracks / Bent CrossmembersRepaired ☐

TIRES (in 32nds)

Axis	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	10		100	RO Front	10		100
2	LI Front	9		100	RI Front	10		100
	LO Middle				RO Middle			
2	LI Middle				RI Middle			
	LO Rear	9		100	RO Rear	9		100
3	LI Rear	10		100	RI Rear	10		100

☒ Aerodynamic Side SkirtsRepaired ☐☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage ProperRepaired ☐☒ Lubricant Level in each Wheel End - Fill if necessaryRepaired ☐☒ Wheels - Check for Cracks / Tire MatchingRepaired ☐☒ Tires - free of impermissible damage or wearRepaired ☐☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbsRepaired ☐☒ Metal Flow-Thru Valve Stem CapsRepaired ☐☒ Conspicuity Tape - Slide Panels, Rear Doors, Rear Impact Guard, HeadboardsRepaired ☐☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact GuardRepaired ☐☒ Doors - Proper OperationRepaired ☐☒ Door Hold Backs and Pull Handles - Present & FunctionalRepaired ☐☒ All Hinges, Rollers, Locks - LubricateRepaired ☐☒ Interior Trailer - Floor, Roof, and Side WallsRepaired ☐☒ Interior - Resecure Plywood as NeededRepaired ☐☒ DOT Inspected - Sticker AppliedRepaired ☐☒ California BIT Inspected & PassedRepaired ☐

NOTES:

Brakes (in 8ths)

Axis	Position	Depth
1	LI Front	5/8
	RI Front	
2	LI Middle	
	RI Middle	
3	LI Rear	5/8
	RI Rear	

Hub: 2807458

Engine Hrs: _____

Prot. Timer: _____

Fuel Bkgs: _____

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.27.

Inspection Conducted By:



(Inspector Signature)

Inspection Date:

9-11-26

Print Name:

Heston Arthur

Company Name:

Dedicated Fleet Services, LLC