

Equipment ID 280061 VIN FT649404 Year 2014 Manufacturer Great Dane Primary Plate _____

DOT / BIT Inspection and PM Worksheet

Check Mark = OK

X = Needs Further Attention

R = Repaired

N/A = Not Applicable

☒ Glue Hands & Rubber Grommets	Repaired ☐
☒ 7-Way Electrical Plug	Repaired ☐
☒ Registration, Valid License Plate and sticker	Repaired ☐
☒ Lights, Wiring and Splice Conditions	Repaired ☐
☒ Exterior Trailer - Body Condition and Coupling Device	Repaired ☐
☒ Corner Locking Devices	Repaired ☐
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	Repaired ☐
☒ Fuel Tank and Fuel System (Nozzle)	Repaired ☐
☒ Air Brake System - Test for leaks	Repaired ☐
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks	Repaired ☐
☒ ABS system - Actuate	Repaired ☐
☒ Air Lines - Check for damage / wear / chaffing	Repaired ☐
☒ Suspension Hangers - Free of defects and cracks	Repaired ☐
☒ Air Tank and Mounting Brackets	Repaired ☐
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	Repaired ☐
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired ☐
☒ Suspension / U-Bolts / Springs - Free of defects and cracks	Repaired ☐
☒ Flatbed Winches - Lubricate and Cycle	Repaired ☐
☒ Sub-Frame - Free of Cracks / Bent Crossmembers	Repaired ☐

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	10		150	RO Front	9		150
1	LI Front	10		150	RI Front	10		150
2	LO Middle				RO Middle			
2	LI Middle	9		150	RI Middle	10		150
3	LO Rear				RO Rear	10		150
3	LI Rear	10		150	RI Rear	10		150

Brakes (in 8ths)

Axle	Position	Depth
1	LI Front	5/8
1	RI Front	5/8
2	LI Middle	5/8
2	RI Middle	5/8
3	LI Rear	
3	RI Rear	

☒ Aerodynamic Side Skirts	Repaired ☐
☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	Repaired ☐
☒ Lubricant Level in each Wheel End - Fill if necessary	Repaired ☐
☒ Wheels - Check for Cracks / Tire Matching	Repaired ☐
☒ Tires - Free of Impermissible damage or wear	Repaired ☐
☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	Repaired ☐
☒ Metal Flow-Thru Valve Stem Caps	Repaired ☐
☒ Concealably Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	Repaired ☐
☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard	Repaired ☐
☒ Doors - Proper Operation	Repaired ☐
☒ Door Hold Backs and Pull Handles - Present & Functional	Repaired ☐
☒ All Hinges, Rollers, Locks - Lubricate	Repaired ☐
☒ Interior Trailer - Floor, Roof, and Side Walls	Repaired ☐
☒ Interior - Resecure Plywood as Needed	Repaired ☐
☒ DOT Inspected - Sticker Applied	Repaired ☐
☒ California BIT Inspected & Passed	Repaired ☐

NOTES:

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396.17, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By: Shawn Teeder Inspector Signature: [Signature]

Inspection Date: 9-11-26

Print Name: Shawn Teeder Company Name: Dedicated Fleet Services, LLC

Hub: 996.0

Engine Hrs: _____

Prod. Time: _____

Fuel Hrs: _____