

Equipment ID: 368090 VIN: HT 368090 Year: 2016 Manufacturer: Hyundai

DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention

☒ Glove Hands & Rubber Grommets Repaired ☐

☒ 7-Way Electrical Plug Repaired ☐

☒ Registration, Valid License Plate and sticker Repaired ☐

☒ Lights, Wiring and Splice Candles Repaired ☐

☒ Exterior Trailer - Body Condition and Coupling Device Repaired ☐

☒ Corner Locking Devices Repaired ☐

☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle Repaired ☐

☒ Fuel Tank and Fuel System (Hoefer) Repaired ☐

☒ Air Brake System - Test for leaks Repaired ☐

☒ Dump Valve (Air Idle Only) - Test operation and check for leaks Repaired ☐

☒ ABS System - Actuate Repaired ☐

☒ Air Lines - Check for damage / wear / chaffing Repaired ☐

☒ Suspension Hangers - Free of defects and cracks Repaired ☐

☒ Air Tank and Mounting Brackets Repaired ☐

☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks Repaired ☐

☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust Repaired ☐

☒ Suspension / U-Bolts / Springs - Free of defects and cracks Repaired ☐

☒ Flatfoot Winches - Lubricate and Cycle Repaired ☐

☒ Sub-Frame - Free of Cracks / Bent Crossmembers Repaired ☐

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front			180	RO Front	12		100
	LI Front			180	RI Front	12		100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	12		100	RO Rear	12		100
	LI Rear	10		100	RI Rear	12		100

Brakes (in 32nds)

Axle	Position	Depth
1	L Front	5/8
	R Front	5/8
2	L Middle	
	R Middle	5/8
3	L Rear	
	R Rear	

R = Repaired N/A = Not Applicable

☒ Aerodynamic Side Skirts Repaired ☐

☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper, Repaired ☐

☒ Lubricant Level in each Wheel End - Fill if necessary Repaired ☐

☒ Wheels - Check for Cracks / Tire Matching Repaired ☐

☒ Tires - Free of Impermissible damage or wear Repaired ☐

☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs Repaired ☐

☒ Metal Flow-Thru Valve Stem Caps Repaired ☐

☒ Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards Repaired ☐

☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard Repaired ☐

☒ Doors - Proper Operation Repaired ☐

☒ Door Hold Backs and Pull Handles - Present & Functional Repaired ☐

☒ All Hinges, Rollers, Locks - Lubricate Repaired ☐

☒ Interior Trailer - Floor, Roof, and Side Walls Repaired ☐

☒ Interior - Resecure Plywood as Needed Repaired ☐

☒ DOT Inspected - Sticker Applied Repaired ☐

☒ California BIT Inspected & Passed Repaired ☐

NOTES:

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.47.

Inspection Conducted By: [Signature] Inspector Signature

Print Name: SHAWN POKER Company Name: Dedicated Fleet Services, LLC

Inspection Date: 8-9-26

Hubo: _____

Engine Hrs: _____

Prod. Time: _____

Fuel Btts: _____