10233 Governor Lane Blvd			
P.O.	Box 433 y	Villiamsport, MI	Inspection Location: Delanco (Branch ID, City & State)
. – (2	MO) 035-6	/33	(Branch ID, City & State)
F-(3	301) 223-7	674	Unit #: 05/-5F Serial # 10778/72YTG050017
		•	MFG/Year <u>Dorsy</u> 96 Serial #. <u>DTP86Z2XTG050017</u> Date of Inspection: <u>10-22-15</u>
0"		i	
OK.	DEFECT	N/A	(Month / Day / Year)
DX.	Ω	10	Registration valid installed in Registration Holder.
~			License Plate # 1765295 State MW Expiration: 2-17
, ES	[]		Conspicuity Tape sides, rear ICC Assembly and rear doors (top & bottom).
X			All Marker, Clearance, Stop/Turn, Flashers and License Plate Lights are operational. All Electric
8	19600	A.	Harnesses are secured properly. Seven way plug properly secured.
X	[]		All Front and side panels are free of holes or damage. Top and bottom rails, front top rails and lower
1			Rails are free of damage, properly fastened to cross members, posts and panels.
N		. []	
/ \		3 1340	ICC assembly is properly secured, step is secure and functional and has reflective tape installed.  Taillights are functioning properly, rear doors close and lock properly and have reflective tape installed.
$\checkmark$	_		top and bottom. Mud flaps and brackets are installed and secure.
×			Air Ride Suspension Spring Ride Suspension X
1			Springs, Rebound bolts, U-Bolts, Equalizers, Radius Rods, are free of damage, excessive wear
( ,			Secure and free of defects. Air bags are intact, shocks are properly installed, free of excessive oil and Leaks, brackets are attached and secure.
by	D	. 🖸	Slider Rails are properly secured to the cross members, no gaps or broken welds. Slider Pins are properly
			installed and engaged to the slider rails. Slider handle is properly secured. OFM Gussets are introduced to
	29	ore of	Gear straight, braces intact, properly attached to Wing Plate and Cross Members handle in good condition
M	П	D	and able to be properly secured.
/4	L3	. <b>U</b>	All Glad Hand Grommets are free of tears and excessive wear. Glad hands are properly secured to the front
1			Panel/bulkhead; Airlines are secured by a slider return spring. All airlines are free of wear marks, chaffing And defects. Air tanks are properly secured and drained.
M	II .	0	Brake adjustment checked, brake thickness measured, stack adjusters properly secured and operational.
/ \			Manual or Auto Slack > equipped, Spring brakes are not count are fine of
			corrosion. Scale brums are intact, no excess wear or damage, free of oil and grease.
			Front axle brake thickness 60 60
Π	r)	\ \	Rear Axle Brake Thickness 60 60
LJ	. 0	/D\	Optional equipment is functional (Lift Gate), batteries secured properly. Winches & straps properly secured
1 .		'	And in good condition.
10		n	Tires matched (within 5/2 and a madden to 5
$/ \setminus$			Tires matched (within 6/32nds tread depth), free of dry rot, cuts cord or belt exposure, properly inflated.  All lug nuts properly secured, rims are free of cracks, damage, or excessive wear with no oil present on rims.
		i	All hubs are in good condition with proper fluid levels.
TREAD DEPTH 32/NDS"			Radial = R Radial Recap = RRC Bias Ply = B
POSIT	TION	. TREAD DEPTH	IDE DOCTOR
LFO		10	RFO TREAD DEPTH LBS CONST: AZ
LFI		_6	A RFI
LRO			A RRO ETNOCK:
LRI	88	<u></u>	RRI 13 0 COS DOSTCO
HUBOMETER 22816			7/2:20
0.000			Tire Size 4022.5 RIM TYPE H.P
INSPECTED BY: To:			
PRINT NAME			4/2
			SIGNATURE
RIIFICA	TION: THIS	VEHICLE HAS PASSI	ED ALL THE INSPECTION ITEMS FOR THE ANNUAL INSPECTION REPORT IN ACCORDANCE WITH 49 CFR 396.
			THE ANNUAL INSPECTION REPORT IN ACCORDANCE WITH AS CO.
		3	- WIII 49 CFR 396.