

## Record of Annual Inspection

The inspector of this vehicle meets the qualification requirements contracted in D.O.T. rule 49 CFR section 396.19

		Governor Lane			nspection Lo	cation:		NDO, FLORIDA	
		[15] . [15] [15] [15] [15] [15] [15] [15] [15]	port, MD 21795-073		D. ATE ID DE	DADIE C	-	Branch ID, City & State)	
	•	0) 635-6733	Unit #: 10007.	V	erial #: 1 PTo 1	ADABLE -	TES OR	NO - (circle one)	
	F - (30	1) 223-7674	MFG/Year T/m 2cv		erial #: 1 P VO I		11/20	015	
			WIFG/ Teal 1/M ACC	2	ate of Inspection	(Month / D	The state of the s		
OK D	EFECT	N/A							
7	[]		Registration valid installed	in Registration H	older.				
		1	License Plate #	U35710	3 State	Expira	ation:		
Y	[]		Conspicuity Tape sides, rea			& bottom).			
			All Marker, Clearance, Stop Harnesses are secured pro	o/Turn, Flashers	and License Plate L	ights are ope	rational. Al	l Electric	
	[]		All Front and side panels a				front top r	ails and lower	
E.J	r1	LJ	Rails are free of damage,	properly fastened	to cross members	posts and pa	anels.		
	[]	[]	ICC assembly is properly s	ecured, step is se	ecure and functions	and has ref	ective tape	e installed.	
/	1.3		Taillights are functioning p	roperly; rear doo	rs close and lock por prackets are install	operly and ha	eve reflecti	ve tape installed	
1	r ı	n	Air Ride Suspension		. /				
[]	[]		Caringa Dahaund hatta II	Potte Equalizare	Padius Rods are	free of dama	ge, excessi	ive wear.	
/		100	Secure and free of defect	s. Air bags are int	act, shocks are pro	perly installed	d, free of e	xcessive oil and	
/	r3	m	Leaks, brackets are attac Slider Rails are properly s		es members no ga	ns or broken	welds. Slid	ler Pins are properly	
				the didor raile C	ider handle is nron	erly secured.	UEM GUSS	ets are intact. Landing	
			Gear straight,	praces intact, pro	perly attached to v	ring Plate and	Cross Me	mbers handle in good condition	
			and able to be All Glad Hand Grommets	properly secured	and avenesive wea	Glad hands	are proper	rly secured to the front	
1	[]		Panel/bulkhead; Airlines	are secured by a	slider return spring	All airlines a	are free of	wear marks, chaffing	
/		1	and defects. Air tanks are	e properly secure	d and drained.	ll:			
C)	[]		Brake adjustment check	ed, brake thickne	ss measured, slack	adjusters pr	operly secu	ured and operational.	
E.3	23		Manual or Auto Sla corrosion. Brake Drums	ck equippe	d Spring brakes a	e not cageu.	are nee or	EXCESSIVE TOOL GIVE	
					LEFT RIGHT				
			Front axle bra Rear Axle Bra	ke Thickness	418 4/4				
[]	[]	Ð	Optional equipment is fu	inctional (Lift Gat	e), batteries secure	d properly. W	linches & s	straps properly secured	
[]	L.1	13	and in good condition		COMM	1		A CONTRACTOR OF THE PARTY OF TH	
0/	67	ri ri	Tires matched (within 6,	/32nds tread der	th) free of dry rot.	cuts cord or t	elt exposu	ire, properly inflated.	
1	IJ		All lug nuts properly sec	ured, rims are fre	ee of cracks, damag	e, or excessive	ve wear wit	h no oil present on rims.	
		i e	All hubs are in good cor	dition with prope	r fluid levels.				
		1		. Dodiol	Recap = RRC	Bias PI	v = <b>B</b>	CIRCLE ONE	
		D DEPTH 32/ND	S" Radial = R AD DEPTH LBS P	OSITION	TREAD DEPTI				
	POSIT		95	RFO	9	93	-	DOOR - SWING OF ROLL	
	LFI			RFI		1	- 1	ROOF - ALUM or TRANS	
	LRC	The second secon		RRO RRI	7				
	LRI						I	ETRAC or LOG POST or N	ONE
	Do	es unit have SI	kyBitz - YES or NO	- circle one			- 1 1	(Please circle one)	
			# ## ### ### #########################		•		11	SIDE PANEL - Propolo	
	Sky	Bitz Serial Nur	nber:				<u>-</u>   L		
			0	10-1			10 A	AND 8 = # OF LUGS	
	HUE	BOMETER 12	Tire Size	MP 97.5	RIM TYPE	HP10/	HP8 / I	BUDD10/ BUDD8 / SPOR	E
				v		1	h		
		ECTED BY:	PRINT NAME			SIGNA	TURE	1	
CER	TIFICATIO	N: THIS VEHICLE H	AS PASSED ALL THE INS	PECTION ITEMS	FOR THE ANNUA	INSPECTION	ON REPOR	RT IN ACCORDANCE WITH 49 CF	R 39