

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
12883	120521
DATE 11/21/18	

MOTOR CARRIER OPERATOR Bauman Sales & Equipment LLC	INSPECTOR'S NAME (PRINT OR TYPE) Robert J. Smith
ADDRESS P.O. Box 857	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Augusta ME 04332-0857	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 1GRAA0627YS023520
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED					
OK	NEEDS REPAIR	REPAIRED DATE		ITEM	
1. BRAKE SYSTEM					
/			a.	Service Brakes	
/			b.	Parking Brake System	
/			c.	Brake Drums or Rotors	
/			d.	Brake Hose	
/			e.	Brake Tubing	
NA			f.	Low Pressure Warning Device	
			g.	Tractor Protection Valve	
			h.	Air Compressor	
			i.	Electric Brakes	
			j.	Hydraulic Brakes	
			k.	Vacuum Systems	
			l.	Antilock Brake System	
			m.	Automatic Brake Adjusters	
2. COUPLING DEVICES					
			a.	Fifth Wheels	
			b.	Pintle Hooks	
			c.	Drawbar/Towbar Eye	
			d.	Drawbar/Towbar Tongue	
			e.	Safety Devices	
			f.	Saddle-Mounts	
3. EXHAUST SYSTEM					
			a.	Exhaust system leaking forward of or directly below the driver/sleeper compartment.	
			b.	Bus exhaust system leaking or discharging in violation of standard.	
			c.	Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	
4. FUEL SYSTEM					
			a.	Visible leak.	
			b.	Fuel tank filler cap missing.	
			c.	Fuel tank securely attached.	
5. LIGHTING DEVICES					
			All lighting devices and reflectors required by Part 393 shall be operable.		
6. SAFE LOADING					
/			a.	Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	
/			b.	Protection against shifting cargo.	
/			c.	Container securement devices on intermodal equipment.	
7. STEERING MECHANISM					
NA			a.	Steering Wheel Free Play	
			b.	Steering Column	
			c.	Front Axle Beam and All Steering Components Other Than Steering Column	
			d.	Steering Gear Box	
			e.	Pitman Arm	
			f.	Power Steering	
			g.	Ball and Socket Joints	
			h.	Tie Rods and Drag Links	
			i.	Nuts	
			j.	Steering System	
8. SUSPENSION					
/			a.	Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	
/			b.	Spring Assembly	
/			c.	Torque, Radius or Tracking Components	
9. FRAME					
/			a.	Frame Members	
/			b.	Tire and Wheel Clearance	
/			c.	Adjustable Axle Assemblies (Sliding Subframes)	
10. TIRES					
NA			a.	Tires on any steering axle of a power unit.	
/			b.	All other tires.	
/			c.	Installation of speed-restricted tires unless specifically designated by motor carrier.	
11. WHEELS AND RIMS					
NA			a.	Lock or Side Ring	
/			b.	Wheels and Rims	
/			c.	Fasteners	
/			d.	Welds	
12. WINDSHIELD GLAZING					
NA			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).		
13. WINDSHIELD WIPERS					
			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.		
14. MOTORCOACH SEATS					
			Any passenger seat that is not securely fastened to the vehicle structure.		
15. OTHER					
			List any other condition(s) which may prevent safe operation of this vehicle. _____ _____ _____ _____ _____		

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: / OK X NEEDS REPAIR NA IF ITEMS DO NOT APPLY. REPAIRED DATE _____

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.