

RECORD OF ANNUAL INSPECTION

TrL# 119659

INSPECTOR'S NAME Ed Bischoff DATE OF INSPECTION 8-17-2020

MOTOR CARRIER NAME BS+E

ADDRESS PO Box 433 CITY Williamsport STATE MD ZIP CODE 21795

VEHICLE IDENTIFICATION NUMBER YT007059 U407185 Tenn. Hub0-061676

TYPE OF VEHICLE 8-1999 Hyundai MODEL Van

VEHICLE COMPONENTS / RESULT OF INSPECTION

COMPONENT	PASS	FAIL	COMPONENT	PASS	FAIL	COMPONENT	PASS	FAIL	COMPONENT	PASS	FAIL
Brake Systems			Fuel System			Steering Mechanism			Tires		
Service Brakes	50%		Leaks			Steering Wheel Free Play			Treads	11/32	
Parking Brakes	✓		Caps			Steering Column			Labeled		
Brake Drums	✓		Bolts / Brackets			Front Axle Beam	✓		"Not for Highway Use"		
Brake Rotors	✓		Lighting System			Steering Components			Markings		
Brake Hoses	✓		Headlights			Gear Box			Mixed Tires on Same Axle	✓	
Brake Tubing	✓		Turn Signals			Pitman Arm			Flaps	✓	
Low Pressure Warning Devices			Identification			Power Steering			Regrooves	✓	
Tractor Protection Valve			Tail Lights			Ball & Socket Joints			Repair Work		
Air Compressor			Stop Lights			Tie Rods and Drag Links			Excess Load Limits		
Electric Brakes			Clearance			Nuts	✓		Contact with Vehicle		
Hydraulic Brakes			Reflectors			Steering System	✓		Leaks		
Vacuum System			License Plate Lights (Rear)			Suspension			Other		
Coupling Devices			Fifth Wheel			U-Bolts	✓		Wheels & Rims		
Fifth Wheel			Hazard Warning			Spring Hangers	✓		Lock or Side Ring	✓	
Pintle Hooks			Other			Axle Positioning Parts	✓		Wheels & Rims	✓	
Drawbar/Towbar Eye			Safe Loading Systems			Spring Assembly	✓		Fasteners	✓	
Drawbar/Towbar Tongue	✓		Parts			Torque, Radius or Tracking	✓		Welds	✓	
Safety Devices			Condition			Frame			Windshield Glazing		
Saddle Mounts			Protection Against Shifting Cargo			Frame Members	✓		Cracks		
Exhaust System						Tire & Wheel Clearance	✓		Discoloration		
Leaks						Adjustable Axle Assemblies (Sliding Subframes)	✓		Vision Reducing Matter		
Location									Windshield Wipers		
									Inoperative		
									Missing or Damaged Parts		

Notes: _____

I certify the accuracy and completeness of this inspection. This inspection complies with all the requirements of 49CFR parts 396.17, 396.21 and Appendix G.

Ed Bischoff
INSPECTOR'S SIGNATURE

8-17-2020
DATE