# RECORD OF ANNUAL INSPECTION

Trl # 241450

Ed Bischoff — INSPECTOR'S NAME

1-16-2021 — DATE OF INSPECTION

BS+E — MOTOR CARRIER NAME

PO Box 433 — ADDRESS

Williamsport — CITY

Md — STATE

21795 — ZIP CODE

5E502614 — VEHICLE IDENTIFICATION NUMBER

665921 Tenn.

Hub0-065072

4-2004 Strick — TYPE OF VEHICLE

Van — MODEL

## VEHICLE COMPONENTS / RESULT OF INSPECTION

| COMPONENT | PASS | FAIL |
|---|---|---|
| **Brake Systems** | | |
| Service Brakes | 75% | |
| Parking Brakes | ✓ | |
| Brake Drums | ✓ | |
| Brake Rotors | | |
| Brake Hoses | ✓ | |
| Brake Tubing | ✓ | |
| Low Pressure Warning Devices | | |
| Tractor Protection Valve | | |
| Air Compressor | | |
| Electric Brakes | | |
| Hydraulic Brakes | | |
| Vacuum System | | |
| **Coupling Devices** | | |
| Fifth Wheel | | |
| Pintle Hooks | | |
| Drawbar/Towbar Eye | | |
| Drawbar/Towbar Tongue | ✓ | |
| Safety Devices | | |
| Saddle Mounts | | |
| **Exhaust System** | | |
| Leaks | | |
| Location | | |

| COMPONENT | PASS | FAIL |
|---|---|---|
| **Fuel System** | | |
| Leaks | | |
| Caps | | |
| Bolts / Brackets | | |
| **Lighting System** | | |
| Headlights | ✓ | |
| Turn Signals | ✓ | |
| Identification | ✓ | |
| Tail Lights | ✓ | |
| Stop Lights | ✓ | |
| Clearance | ✓ | |
| Reflectors | ✓ | |
| License Plate Lights (Rear) | ✓ | |
| Fifth Wheel | | |
| Hazard Warning | ✓ | |
| Other | | |
| **Safe Loading Systems** | | |
| Parts | ✓ | |
| Condition | ✓ | |
| Protection Against Shifting Cargo | ✓ | |

| COMPONENT | PASS | FAIL |
|---|---|---|
| **Steering Mechanism** | | |
| Steering Wheel Free Play | | |
| Steering Column | | |
| Front Axle Beam | | |
| Steering Components | ✓ | |
| Gear Box | | |
| Pitman Arm | | |
| Power Steering | | |
| Ball & Socket Joints | | |
| Tie Rods and Drag Links | | |
| Nuts | ✓ | |
| Steering System | | |
| **Suspension** | | |
| U-Bolts | ✓ | |
| Spring Hangers | ✓ | |
| Axle Positioning Parts | ✓ | |
| Spring Assembly | ✓ | |
| Torque, Radius or Tracking | ✓ | |
| **Frame** | | |
| Frame Members | ✓ | |
| Tire & Wheel Clearance | ✓ | |
| Adjustable Axle | ✓ | |
| Assemblies (Sliding Subframes) | ✓ | |

| COMPONENT | PASS | FAIL |
|---|---|---|
| **Tires** | | |
| Treads | 11/32" | |
| Labeled "Not for Highway Use" | | |
| Markings | | |
| Mixed Tires on Same Axle | ✓ | |
| Flaps | ✓ | |
| Regrooves | ✓ | |
| Repair Work | | |
| Excess Load Limits | | |
| Contact with Vehicle | | |
| Leaks | | |
| Other | | |
| **Wheels & Rims** | | |
| Lock or Side Ring | ✓ | |
| Wheels & Rims | ✓ | |
| Fasteners | ✓ | |
| Welds | ✓ | |
| **Windshield Glazing** | | |
| Cracks | | |
| Discoloration | | |
| Vision Reducing Matter | | |
| **Windshield Wipers** | | |
| Inoperative | | |
| Missing or Damaged Parts | | |

Notes: _____

I certify the accuracy and completeness of this inspection. This inspection complies with all the requirements of 49CFR parts 396.17, 396.21 and Appendix G.

Ed Bischoff — INSPECTOR'S SIGNATURE

1-16-2021 — DATE