ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
16159	2374 RT	6-13-25

MOTOR CARRIER OPERATOR: Bowman Sales and Equipment Goodwill

ADDRESS: 10233 Governor Lane BLVD

CITY, STATE, ZIP CODE: Williamsport / MD 21795

VEHICLE TYPE: ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE): Clifford Akers

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: 1GRAA9629TB105925

INSPECTION AGENCY/LOCATION (OPTIONAL):

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
			f. Low Pressure Warning Device
N/A			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
N/A			a. Fifth Wheels
			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
N/A			e. Safety Devices
			f. Saddle-Mounts
			3. EXHAUST SYSTEM
			a. No leaks forward of/ directly below the driver/ sleeper compartment.
N/A			b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
			4. FUEL SYSTEM
N/A			a. No visible leak.
			b. Fuel Tank Filler Cap
✓			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			6. SAFE LOADING
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
✓			c. Intermodal Container Securement Devices
			7. STEERING MECHANISM
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam/All Other Steering Components
N/A			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
			8. SUSPENSION
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
N/A			a. Steer-Axle Tires
			b. All Other Tires
N/A			c. Speed-Restricted Tires
			11. WHEELS AND RIMS
✓			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			12. WINDSHIELD GLAZING
N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
N/A			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
N/A			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL