ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
16146	24114	6-12-25

MOTOR CARRIER OPERATOR: Bowman Sales and Equipment

ADDRESS: 10233 Governor Lane BLVD

CITY, STATE, ZIP CODE: Williamsport MD 21795

VEHICLE TYPE: ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE): Clifford Akers

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: 1S12953356502276

INSPECTION AGENCY/LOCATION (OPTIONAL):

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
			f. Low Pressure Warning Device
			g. Tractor Protection Valve
			h. Air Compressor
N/A			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
N/A			a. Fifth Wheels
			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
N/A			e. Safety Devices
			f. Saddle-Mounts
			3. EXHAUST SYSTEM
			a. No leaks forward of/ directly below the driver/ sleeper compartment.
N/A			b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
			4. FUEL SYSTEM
			a. No visible leak.
			b. Fuel Tank Filler Cap
N/A			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			6. SAFE LOADING
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
✓			c. Intermodal Container Securement Devices
			7. STEERING MECHANISM
			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
			d. Steering Gear Box
N/A			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
			8. SUSPENSION
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
N/A			a. Steer-Axle Tires
✓			b. All Other Tires
N/A			c. Speed-Restricted Tires
			11. WHEELS AND RIMS
✓			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			12. WINDSHIELD GLAZING
N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
N/A			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
N/A			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE