

Equipment ID: 112477 VIN: CL674955 Year: 2012 Manufacturer: Webaach Primary Plate:
 DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention

☒ GND Hands & Rubber Grommets ☐ Repaired ☐
☒ 7-Way Electrical Plug ☐ Repaired ☐
☒ Registration, Valid License Plate and sticker ☐ Repaired ☐
☒ Lights, Wiring and Splice Conditions ☐ Repaired ☐
☒ Exterior Trailer - Body Condition and Coupling Device ☐ Repaired ☐
☒ Coupler Locking Devices ☐ Repaired ☐
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle ☐ Repaired ☐
☒ Fuel Tank and Fuel System (Roofier) ☐ Repaired ☐
☒ Air Brake System - Test for Leaks ☐ Repaired ☐
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks ☐ Repaired ☐
☒ Air System - Actuate ☐ Repaired ☐
☒ Lines - Check for damage / wear / chaffing ☐ Repaired ☐
☒ Suspension Hangers - Free of defects and cracks ☐ Repaired ☐
☒ Tank and Mounting Brackets ☐ Repaired ☐
☒ Axles - Drums / Linings / Air Chambers - free of defects and cracks ☐ Repaired ☐
☒ Shock Adjusters / S-cams / Brake adjustment - Lubricate & adjust ☐ Repaired ☐
☒ Suspension / U-Bolts / Springs - Free of defects and cracks ☐ Repaired ☐
☒ Shock Absorbers - Lubricate and Cycle ☐ Repaired ☐
☒ Frame - Free of Cracks / Bent Crossmembers ☐ Repaired ☐

R = Repaired N/A = Not Applicable

☒ Aerodynamic Side Skirts ☐ Repaired ☐
☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper ☐ Repaired ☐
☒ Lubricant Level in each Wheel End - Fill if necessary ☐ Repaired ☐
☒ Wheels - Check for Cracks / Tire Matching ☐ Repaired ☐
☒ Tires - free of impermissible damage or wear ☐ Repaired ☐
☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs ☐ Repaired ☐
☒ Metal Flow-Thru Valve Stem Caps ☐ Repaired ☐
☒ Consistently Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards ☐ Repaired ☐
☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard ☐ Repaired ☐
☒ Doors - Proper Operation ☐ Repaired ☐
☒ Door Hold Backs and Pull Handles - Present & Functional ☐ Repaired ☐
☒ All Hinges, Rollers, Locks - Lubricate ☐ Repaired ☐
☒ Interior Trailer - Floor, Roof, and Side Walls ☐ Repaired ☐
☒ Interior - Reseal Plywood as Needed ☐ Repaired ☐
☒ DOT Inspected - Sticker Applied ☐ Repaired ☐
☒ California BIT Inspected & Passed ☐ Repaired ☐

NOTES:

Tires (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	10		100	RO Front	9		100
1	LI Front	9		100	RI Front	10		100
2	LO Middle				RO Middle			
2	LI Middle				RI Middle			
3	LO Rear	10		100	RO Rear	9		100
3	LI Rear	9		100	RI Rear	10		100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	5/8
1	R Front	5/8
2	L Middle	
2	R Middle	
3	L Rear	5/8
3	R Rear	

Hub: 1649862
 Engine Hrs:
 Prot. Time:
 Fuel Bkts:

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.27.

Inspection Conducted By: Preston (Inspector Signature)
 Inspection Date: 9.10.26
 Print Name: Preston
 Company Name: Dedicated Fleet Services, LLC