

ANNUAL VEHICLE INSPECTION REPORT

TruckServiceExperts®

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	154695
DATE 9/15/26	

MOTOR CARRIER OPERATOR

Bowman Trailer Leasing

ADDRESS
45 Paxon CtCITY, STATE, ZIP CODE
Gaston, SC 29053VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

Paul LaFrance

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☒ LIC. PLATE NO. ☐ VIN ☐ OTHER

U495808

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒	☒		1. BRAKE SYSTEM	☒	☒		6. SAFE LOADING	☒	☒		12. WINDSHIELD GLAZING
☒	☒		a. Service Brakes	☒	☒		a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒	☒		No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒	☒		b. Parking Brake System	☒	☒		b. Front End Structure	☒	☒		13. WINDSHIELD WIPERS
☒	☒		c. Brake Drums or Rotors	☒	☒		c. Intermodal Container Securement Devices	☒	☒		No missing, damaged, or inoperable wipers.
☒	☒		d. Brake Hose	☒	☒		7. STEERING MECHANISM	☒	☒		14. MOTORCOACH SEATS
☒	☒		e. Brake Tubing	☒	☒		a. Steering Wheel Free Play	☒	☒		Seats securely fastened to the vehicle structure.
☒	☒		f. Low Pressure Warning Device	☒	☒		b. Steering Column	☒	☒		15. REAR IMPACT GUARD
☒	☒		g. Tractor Protection Valve	☒	☒		c. Front Axle Beam/All Other Steering Components	☒	☒		In place, securely attached, proper size, proper placement (see 393.86).
☒	☒		h. Air Compressor	☒	☒		d. Steering Gear Box	☒	☒		16. OTHER
☒	☒		i. Electric Brakes	☒	☒		e. Pitman Arm	☒	☒		List any other condition(s) which may prevent safe operation of this vehicle.
☒	☒		j. Hydraulic Brakes	☒	☒		f. Power Steering	☒	☒		
☒	☒		k. Vacuum Systems	☒	☒		g. Ball and Socket Joints	☒	☒		
☒	☒		l. Antilock Brake System	☒	☒		h. Tie Rods and Drag Links	☒	☒		
☒	☒		m. Automatic Brake Adjusters	☒	☒		i. Nuts	☒	☒		
☒	☒		2. COUPLING DEVICES	☒	☒		j. Steering System	☒	☒		
☒	☒		a. Fifth Wheels	☒	☒		8. SUSPENSION	☒	☒		
☒	☒		b. Pintle Hooks	☒	☒		a. Axle Positioning Parts	☒	☒		
☒	☒		c. Drawbar/Towbar Eye	☒	☒		b. Spring Assembly	☒	☒		
☒	☒		d. Drawbar/Towbar Tongue	☒	☒		c. Torque, Radius or Tracking Components	☒	☒		
☒	☒		e. Safety Devices	☒	☒		9. FRAME	☒	☒		
☒	☒		f. Saddle-Mounts	☒	☒		a. Frame Members	☒	☒		
☒	☒		3. EXHAUST SYSTEM	☒	☒		b. Tire and Wheel Clearance	☒	☒		
☒	☒		a. No leaks forward of/ directly below the driver/sleeper compartment.	☒	☒		c. Adjustable Axle Assemblies (Sliding Subframes)	☒	☒		
☒	☒		b. Bus: No leaking/ discharging in violation of standard.	☒	☒		10. TIRES	☒	☒		
☒	☒		c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒	☒		a. Steer-Axle Tires	☒	☒		
☒	☒		4. FUEL SYSTEM	☒	☒		b. All Other Tires	☒	☒		
☒	☒		a. No visible leak.	☒	☒		c. Speed-Restricted Tires	☒	☒		
☒	☒		b. Fuel Tank Filler Cap	☒	☒		11. WHEELS AND RIMS	☒	☒		
☒	☒		c. Fuel tank securely attached.	☒	☒		a. Lock or Side Ring	☒	☒		
☒	☒		5. LIGHTING DEVICES	☒	☒		b. Wheels and Rims	☒	☒		
☒	☒		All required lights/reflectors operable.	☒	☒		c. Fasteners	☒	☒		
☒	☒			☒	☒		d. Welds	☒	☒		

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ X NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.