


FHWA / PM INSPECTION

Trailer



DATE: 9/11/26

UNIT #: 246895

YEAR: 2009

CUSTOMER: Bowman

VIN# 1J5V 532WX9L178849

MAKE: WABASH

VEHICLE LOCATION: 400 Acworth Dr
NORTHINGTON, PA

LICENSE PLATE #: U964572

MILEAGE:

Box after each item indicates condition of inspection point.

(✓) Item is OK (D) Item found DEFECTIVE (R) Item has been REPAIRED (N/A) NOT APPLICABLE (L) TRAILER LOADED

Line items with an asterisk (*) indicate inspection points that must meet Federal Motor Carrier Safety Administration (FMCSA) regulations.

SAFETY LANE INSPECTION			INTERIOR INSPECTION CONT'D		
IC	Seq	Description	IC	Seq	Description
✓	1	ASSESS WORK SITE FOR SAFE OPERATION	✓	31	INSPECT CONDITION OF "E" TRACK
✓	2	ENSURE THE NECESSARY PPE/MATERIAL HANDLING DEVICES ARE AVAILABLE	✓	32	INSPECT CONDITION OF ROOF
✓	3	PHOTOGRAPH TRAILER UNIT NUMBER	✓	33	INSPECT CONDITION OF REAR HEADER*
N/A	4	PHOTOGRAPH TRAILER HUBOMETER	N/A	34	INSPECT CONDITION/OPERATION OF REAR OVERHEAD DOOR (HINGES, CABLES, ETC.) LUBRICATE AS NECESSARY.
✓	5	PHOTOGRAPH TRAILER VIN PLATE	✓	35	INSPECT CONDITION OF ROOF BOWS
EXTERIOR BODY INSPECTION			LOWER CHASSIS INSPECTION		
✓	6	INSPECT KING PIN FOR WEAR/MOUNTING*	✓	36	INSPECT CONDITION/MOUNTING OF TORQUE ARMS - BOLT/BUSHINGS*
✓	7	INSPECT KING PIN PLATE FOR STRUCTURAL DAMAGE*	✓	37	INSPECT CONDITION/MOUNTING OF "U" BOLTS/SPRINGS, SHOCK ABSORBERS*
✓	8	INSPECT CONDITION AND MOUNTING OF GLADHANDS*	R	38	INSPECT CONDITION/MOUNTING OF TRAILER AXLES/ST AIR SUSPENSION, AIR BAGS, SYSTEM FAILURE, LEAK, ETC. (IF APPLICABLE)*
✓	9	INSPECT CONDITION OF GLADHAND SEALS*	✓	39	INSPECT WHEEL SEALS FOR LEAKS/SEEPAGE*
✓	10	INSPECT CONDITION OF LIGHT/CORD RECEPTACLE	✓	40	INSPECT BRAKE LINING TO MEET DOT REQUIREMENTS*
✓	11	INSPECT CONDITION/MOUNTING OF LANDING GEAR LEGS	✓	41	INSPECT CONDITION OF BRAKE DRUMS*
✓	12	INSPECT SPARE TIRE RACK	✓	42	INSPECT RELAY VALVE OPERATION*
✓	13	INSPECT CONDITION, MOUNTING AND OPERATION OF ALL LIGHTS AND REFLECTORS*	✓	43	INSPECT ALL AIR LINES FOR WEAR/TOUCHING/AIR LEAKS*
R	14	INSPECT CONDITION OF FRONT HEADER*	✓	44	INSPECT CONDITION OF ALL VALVES, BRAKE CHAMBERS, FITTINGS, ETC. FOR AIR LEAKS*
✓	15	INSPECT CONDITION OF BODY PANELS*	✓	45	INSPECT CONDITION/MOUNTING OF AIR TANKS*
✓	16	INSPECT CONDITION OF TOP RAILS*	✓	46	INSPECT BRAKE OPERATION AND PUSH ROD TRAVEL*
✓	17	INSPECT CONDITION OF BOTTOM RAILS*	✓	47	INSPECT OPERATION OF ANTI-LOCK BRAKE SYSTEM IF APPLICABLE*
✓	18	INSPECT FOR LOOSE OR MISSING RIVETS AT CROSSMEMBERS*	✓	48	DRAIN AIR TANKS
✓	19	INSPECT CONDITION OF SUB FRAME*	✓	49	LUBRICATE ENTIRE CHASSIS AS REQUIRED
✓	20	INSPECT CONDITION OF EXTERIOR FLOORING (IF TRAILER LOADED)	✓	50	INSPECT HUB OIL LEVELS - CORRECT AS NECESSARY*
✓	21	INSPECT CONDITION/OPERATION OF TANDEM AXLE SLIDE AND PINS (INCLUDING STOP BARS & SAFETY'S)*	R	51	INSPECT VALVE CAPS AND AIR TUBES TO SPECS*
✓	22	INSPECT CONDITION OF REAR HEADER*	✓	52	INSPECT WHEEL LUG NUTS FOR TIGHTNESS*
✓	23	INSPECT CONDITION OF REAR SILL	✓	53	RE-TORQUE LUG NUTS TO OEM SPECIFICATION*
✓	24	INSPECT CONDITION OF REAR DOORS (INCLUDING SEALS)	✓	54	INSPECT CONDITION OF RIMS / WHEELS*
✓	25	INSPECT CONDITION OF REAR DOOR HOLD-BACKS	✓	55	INSPECT TIRE CONDITION, TREAD DEPTH AND MATCHING*
✓	26	INSPECT CONDITION OF REAR BUMPER*	✓	56	INSPECT TRAILER AXLE ALIGNMENT
✓	27	INSPECT CONDITION/MOUNTING OF MUD FLAPS*	✓	57	APPLY INSPECTION DECAL - REMOVE OLD DECALS AND PAPERWORK*
INTERIOR BODY INSPECTION			TIRE INSPECTION & BRAKE MEASUREMENTS		
✓	28	INSPECT CONDITION OF FLOORING	✓	58	INSPECT AND RECORD TREAD DEPTHS IN 32ND'S*
✓	29	INSPECT CONDITION OF SIDEWALLS & SCUFF	✓	59	INSPECT AND RECORD BRAKE LINING THICKNESS IN 32ND'S*
✓	30	INSPECT CONDITION OF NOSE OF TRAILER			

FHWA / PM INSPECTION

Trailer



Pass



Fail



DATE: 9/11/26

CUSTOMER: Bowman

VEHICLE LOCATION: 400 Hockwith Dr
Nortonhampton, PA

UNIT #: 29 246895

VIN# 1JTV532W9L178849

LICENSE PLATE #: 4964572

YEAR: 2009

MAKE: WABASH

MILEAGE:

Box after each item indicates condition of inspection point.

(✓) Item is OK

(D) Item found DEFECTIVE

(R) Item has been REPAIRED

(N/A) NOT APPLICABLE

(L) TRAILER LOADED

Line items with an asterisk (*) indicate inspection points that must meet Federal Motor Carrier Safety Administration (FMCSA) regulations.

TIRE INSPECTION					BRAKE MEASUREMENTS		
AXLE 1	LO: 6	LI: 2	RI: 3	RO: 12	AXLE 1	L: 16	R: 18
AXLE 2	LO: 14	LI: 13	RI: 8	RO: 10	AXLE 2	L: 16	R: 18
AXLE 3	LO:	LI:	RI:	RO:	AXLE 3	L:	R:
AXLE 4	LO:	LI:	RI:	RO:	AXLE 4	L:	R:
AXLE 5	LO:	LI:	RI:	RO:	AXLE 5	L:	R:
AXLE 6	LO:	LI:	RI:	RO:	AXLE 6	L:	R:
AXLE 7	LO:	LI:	RI:	RO:	AXLE 7	L:	R:
AXLE 8	LO:	LI:	RI:	RO:	AXLE 8	L:	R:

Inspector's Signature:

Steve Giff

Date:

9/11/26

I hereby certify that this vehicle has passed all of the inspection items for the annual inspection report in accordance with 49 CFR 396.

Revised 12/2024