

Equipment ID: 328023 VIN: FT329023 Year: 2015 Manufacturer: Hyundai Primary Plate: _____

DOT / BIT Inspection and PM Worksheet

Check Mark = OK

X = Needs Further Attention

R = Repaired

N/A = Not Applicable

☒ Global Hands & Rubber Grams	☐ Repaired	☒ Aerodynamic Side Skirts	☐ Repaired
☒ Electrical Plug	☐ Replaced	☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	☐ Replaced
☒ Registration, Valid License Plate and sticker	☐ Replaced	☒ Lubricant Level in each Wheel End - Fill if necessary	☐ Replaced
☒ Wiring and Splice Conditions	☐ Replaced	☒ Wheels - Check for Cracks / Tires Matching	☐ Replaced
☒ Exterior Trailer - Body Condition and Coupling Device	☐ Replaced	☒ Tires - free of impermissible damage or wear	☐ Replaced
☒ Corrosion Locking Devices	☐ Replaced	☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	☐ Replaced
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	☐ Replaced	☒ Metal Flow-Thru Valve Stem Caps	☐ Replaced
☒ Fuel Tank and Fuel System (Roof)	☐ Replaced	☒ Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	☐ Replaced
☒ Air Valve System - Test for Leaks	☐ Replaced	☒ Mullflaps, Brackets, Rubber Deck Bumpers, and Rear Impact Guard	☐ Replaced
☒ Air Valve (Air Ride Only) - Test operation and check for Leaks	☐ Replaced	☒ Doors - Proper Operation	☐ Replaced
☒ AB System - Actuate	☐ Replaced	☒ Door Hold Backs and Pull Handles - Present & Functional	☐ Replaced
☒ Air Lines - Check for damage / wear / chaffing	☐ Replaced	☒ All Hinges, Rollers, Locks - Lubricate	☐ Replaced
☒ Suspension Hangers - Free of defects and cracks	☐ Replaced	☒ Interior Trailer - Floor, Roof, and Side Walls	☐ Replaced
☒ Air Tank and Mounting Brackets	☐ Replaced	☒ Interior - Resecure Plywood as Needed	☐ Replaced
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	☐ Replaced	☒ DOT Inspected - Sticker Applied	☐ Replaced
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	☐ Replaced	☒ California BIT Inspected & Passed	☐ Replaced
☒ Slack / Suspension / U-Bolts / Springs - Free of defects and cracks	☐ Replaced		
☒ Slack / Winches - Lubricate and Cycle	☐ Replaced		
☒ Slack / Frame - Free of Cracks / Bent Crossmembers	☐ Replaced		

TIRES (in 32nds)

Position	ID	Brand	PSI	Position	ID	Brand	PSI
1	9		150	1	8		100
2	9		100	2	8		100
3	9		100	3	8		100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	5/8
1	R Front	5/8
2	L Middle	
2	R Middle	
3	L Rear	5/8
3	R Rear	5/8

Hubo: 22045
 Engine Hrs: _____
 Prot. Time: _____
 Fuel Bkts: _____

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 395, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 395.17.

Inspection Conducted By: Dalton E PP
 (Inspector Signature)

Inspection Date: 9-10-26

Print Name: Dalton E PP Company Name: Dedicated Fleet Services, LLC