

Equipment ID 328132 VIN FT328132 Year 2015 Manufacturer Hyundai Primary Plate _____

DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention

☒ Global Hands & Rubber Grommets	Repaired ☐	☒ Aerodynamic Side Skirts	R = Repaired N/A = Not Applicable
☒ 7-Way Electrical Plug	Repaired ☐	☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	
☒ Registration, Valid License Plate and sticker	Repaired ☐	☒ Lubricant Level in each Wheel End - Fill if necessary	
☒ Lights, Wiring and Splice Conditions	Repaired ☐	☒ Wheels - Check for Cracks / Tire Matching	
☒ Exterior Trailer - Body Condition and Coupling Device	Repaired ☐	☒ Tires - free of impermissible damage or wear	
☒ Corner Locking Devices	Repaired ☐	☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	Repaired ☐	☒ Metal Flow-Thru Valve Stem Caps	
☒ Fuel Tank and Fuel System (if/ever)	Repaired ☐	☒ Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	
☒ Air Brake System - Test for leaks	Repaired ☐	☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard	
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks	Repaired ☐	☒ Doors - Proper Operation	
☒ ABS System - Actuate	Repaired ☐	☒ Door Hold Backs and Pull Handles - Present & Functional	
☒ Air Lines - Check for damage / wear / chaffing	Repaired ☐	☒ All Hinges, Rollers, Locks - Lubricate	
☒ Suspension Hangers - Free of defects and cracks	Repaired ☐	☒ Interior Trailer - Floor, Roof, and Side Walls	
☒ Air Tank and Mounting Brackets	Repaired ☐	☒ Interior - Resecure Plywood as Needed	
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	Repaired ☐	☒ DOT Inspected - Sticker Applied	
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired ☐	☒ California BIT Inspected & Passed	
☒ Suspension / U-bolts / Springs - Free of defects, and cracks	Repaired ☐		
☒ Flatbed Winches - Lubricate and Cycle	Repaired ☐		
☒ Sub-frame - Free of Cracks / Bent Crossmembers	Repaired ☐		

TIRES (in 32nds)

Axle	Position	TP	Brand	PSI	Position	TP	Brand	PSI
1	LO Front	9		180	RO Front	9		180
1	LI Front			180	RI Front			180
2	LO Middle				RO Middle			
2	LI Middle			100	RI Middle			100
3	LO Rear	9		100	RO Rear	9		100
3	LI Rear			100	RI Rear			100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	5/8
1	R Front	
2	L Middle	
2	R Middle	
3	L Rear	5/8
3	R Rear	

Hubo: 25408
 Engine Hrs: _____
 Prot. Time: _____
 Fuel Bkts: _____

NOTES:

by signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396.17, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By: Dg1ton EPP
 (Inspector Signature)

Inspection Date: 9-10-26

Print Name: Dg1ton EPP Company Name: Dedicated Fleet Services, LLC