

Equipment ID: 328414 VIN: ET328414 Year: 2014 Manufacturer: Hyundai Primary Plate: _____

DOT / BIT Inspection and PIM Worksheet

Check Mark = OK X = Needs Further Attention

- ☒ Global Hands & Rubber Grommets ☐ Repaired
- ☒ 7-Way Electrical Plug ☐ Repaired
- ☒ Registration, Valid License Plate and sticker ☐ Repaired
- ☒ Lights, Wiring and Splice Conditions ☐ Repaired
- ☒ Exterior Trailer - Body Condition and Coupling Device ☐ Repaired
- ☒ Corner Locking Devices ☐ Repaired
- ☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle ☐ Repaired
- ☒ Fuel Tank and Fuel System (Heater) ☐ Repaired
- ☒ Air Brake System - Test for leaks ☐ Repaired
- ☒ Dump Valve (Air Ride Only) - Test operation and check for leaks ☐ Repaired
- ☒ ABS System - Actuate ☐ Repaired
- ☒ Air Lines - Check for damage / wear / chaffing ☐ Repaired
- ☒ Suspension Hangers - Free of defects and cracks ☐ Repaired
- ☒ Air Tank and Mounting Brackets ☐ Repaired
- ☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks ☐ Repaired
- ☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust ☐ Repaired
- ☒ Suspension / U-Bolts / Springs - Free of defects and cracks ☐ Repaired
- ☒ Flatbed Winches - Lubricate and Cycle ☐ Repaired
- ☒ Sub-Frame - Free of Cracks / Bent Crossmembers ☐ Repaired

TIRES (in 32nds)

Axle	Position	ID	Brand	PSI	Position	ID	Brand	PSI
1	LO Front	10		100	RO Front	10		100
	LI Front	9		100	RI Front	10		100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	9		100	RO Rear	9		100
	LI Rear	9		100	RI Rear	10		100

R = Repaired N/A = Not Applicable

- ☒ Aerodynamic Side Skirts ☐ Repaired
- ☒ Slider Mechanism & Locking Pins - Lubricate, Retorque, Re-engage Proper ☐ Repaired
- ☒ Lubricant Level in each Wheel End - Fill if necessary ☐ Repaired
- ☒ Wheels - Check for Cracks / Tire Matching ☐ Repaired
- ☒ Tires - free of impermissible damage or wear ☐ Repaired
- ☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs ☐ Repaired
- ☒ Metal Flow-Thru Valve Stem Caps ☐ Repaired
- ☒ Conspectively Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards ☐ Repaired
- ☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard ☐ Repaired
- ☒ Doors - Proper Operation ☐ Repaired
- ☒ Door Hold Backs and Pull Handles - Present & Functional ☐ Repaired
- ☒ All Hinges, Rollers, Locks - Lubricate ☐ Repaired
- ☒ Interior Trailer - floor, roof, and side walls ☐ Repaired
- ☒ Interior - Reseal Plywood as Needed ☐ Repaired
- ☒ DOT Inspected - Sticker Applied ☐ Repaired
- ☒ California BIT Inspected & Passed ☐ Repaired

NOTES:

Brakes (in 6ths)

Axle	Position	Depth
1	L Front	5/8
	R Front	5/8
2	L Middle	5/8
	R Middle	5/8
3	L Rear	5/8
	R Rear	5/8

Hubor: 0
 Engine Hrs: _____
 Prot. Time: _____
 Fuel Bkls: _____

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By:

[Signature]
 Inspector Signature

Inspection Date:

9-10-20

Print Name:

Shawn Taylor

Company Name:

Dedicated Fleet Services, LLC