

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

708235

DATE 9/14/20

MOTOR CARRIER OPERATOR

Bowman

INSPECTOR'S NAME (PRINT OR TYPE)

C. Spearman

ADDRESS

112 Metrogate Ct

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

YES

CITY, STATE, ZIP CODE

Simpsonville SC 29681

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☒ OTHER

708235

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS
☐ (OTHER)

INSPECTION AGENCY/LOCATION (OPTIONAL)

-Pro Suc

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
/			a. Service Brakes	/			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	/			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
/			b. Parking Brake System	/			b. Front End Structure	/			13. WINDSHIELD WIPERS
/			c. Brake Drums or Rotors	/			c. Intermodal Container Securement Devices	/			No missing, damaged, or inoperable wipers.
/			d. Brake Hose	/				/			14. MOTORCOACH SEATS
/			e. Brake Tubing	/				/			Seats securely fastened to the vehicle structure.
NA			f. Low Pressure Warning Device	NA			7. STEERING MECHANISM	/			15. REAR IMPACT GUARD
/			g. Tractor Protection Valve	/			a. Steering Wheel Free Play	/			In place, securely attached, proper size, proper placement (see 393.86).
/			h. Air Compressor	/			b. Steering Column	/			16. OTHER
/			i. Electric Brakes	/			c. Front Axle Beam/All Other Steering Components	/			List any other condition(s) which may prevent safe operation of this vehicle.
/			j. Hydraulic Brakes	/			d. Steering Gear Box	/			1/2 front outside
/			k. Vacuum Systems	/			e. Pitman Arm	/			1/2 rear inside
/			l. Antilock Brake System	/			f. Power Steering	/			
/			m. Automatic Brake Adjusters	/			g. Ball and Socket Joints	/			
			2. COUPLING DEVICES				h. Tie Rods and Drag Links	/			
/			a. Fifth Wheels	/			i. Nuts	/			
/			b. Pintle Hooks	/			j. Steering System	/			
/			c. Drawbar/Towbar Eye	/			8. SUSPENSION	/			
/			d. Drawbar/Towbar Tongue	/			a. Axle Positioning Parts	/			
/			e. Safety Devices	/			b. Spring Assembly	/			
/			f. Saddle-Mounts	/			c. Torque, Radius or Tracking Components	/			
			3. EXHAUST SYSTEM				9. FRAME	/			
/			a. No leaks forward of/ directly below the driver/sleeper compartment.	/			a. Frame Members	/			
/			b. Bus: No leaking/discharging in violation of standard.	/			b. Tire and Wheel Clearance	/			
/			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	/			c. Adjustable Axle Assemblies (Sliding Subframes)	/			
			4. FUEL SYSTEM				10. TIRES	/			
/			a. No visible leak.	/			a. Steer-Axle Tires	/			
/			b. Fuel Tank Filler Cap	/			b. All Other Tires	/			
/			c. Fuel tank securely attached.	/			c. Speed-Restricted Tires	/			
			5. LIGHTING DEVICES				11. WHEELS AND RIMS	/			
/			All required lights/reflectors operable.	/			a. Lock or Side Ring	/			
/				/			b. Wheels and Rims	/			
/				/			c. Fasteners	/			
/				/			d. Welds	/			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.