

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	808409
DATE 9/14/26	

MOTOR CARRIER OPERATOR <u>Bowman</u>	INSPECTOR'S NAME (PRINT OR TYPE) <u>C. Spearman</u>
ADDRESS <u>112 Metrogate Ct</u>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE <u>Simsenville SC 29681</u>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☒ OTHER <u>808409</u>
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) <u>Pro Sec</u>

VEHICLE COMPONENTS INSPECTED								
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	
1. BRAKE SYSTEM								
✓			a. Service Brakes				12. WINDSHIELD GLAZING No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	
✓			b. Parking Brake System					
✓			c. Brake Drums or Rotors					
✓			d. Brake Hose					
✓			e. Brake Tubing					
NA			f. Low Pressure Warning Device					
			g. Tractor Protection Valve					
			h. Air Compressor					
			i. Electric Brakes					
			j. Hydraulic Brakes					
			k. Vacuum Systems					
			l. Antilock Brake System					
			m. Automatic Brake Adjusters					
2. COUPLING DEVICES								
NA			a. Fifth Wheels				13. WINDSHIELD WIPERS No missing, damaged, or inoperable wipers.	
			b. Pintle Hooks					
			c. Drawbar/Towbar Eye					
			d. Drawbar/Towbar Tongue					
			e. Safety Devices					
			f. Saddle-Mounts					
3. EXHAUST SYSTEM								
			a. No leaks forward of/ directly below the driver/ sleeper compartment.					
			b. Bus: No leaking/ discharging in violation of standard.					
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.					
4. FUEL SYSTEM								
			a. No visible leak.					
			b. Fuel Tank Filler Cap					
			c. Fuel tank securely attached.					
5. LIGHTING DEVICES								
✓			All required lights/reflectors operable.					
6. SAFE LOADING								
			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				14. MOTORCOACH SEATS Seats securely fastened to the vehicle structure.	
			b. Front End Structure					
			c. Intermodal Container Securement Devices					
7. STEERING MECHANISM								
			a. Steering Wheel Free Play					
			b. Steering Column					
			c. Front Axle Beam/All Other Steering Components					
			d. Steering Gear Box					
			e. Pitman Arm					
			f. Power Steering					
			g. Ball and Socket Joints					
			h. Tie Rods and Drag Links					
			i. Nuts					
			j. Steering System					
8. SUSPENSION								
			a. Axle Positioning Parts				15. REAR IMPACT GUARD In place, securely attached, proper size, proper placement (see 393.86).	
			b. Spring Assembly					
			c. Torque, Radius or Tracking Components					
9. FRAME								
			a. Frame Members					
			b. Tire and Wheel Clearance					
			c. Adjustable Axle Assemblies (Sliding Subframes)					
10. TIRES								
			a. Steer-Axle Tires					
			b. All Other Tires					
			c. Speed-Restricted Tires					
11. WHEELS AND RIMS								
			a. Lock or Side Ring					
			b. Wheels and Rims					
			c. Fasteners					
			d. Welds					
16. OTHER List any other condition(s) which may prevent safe operation of this vehicle.								

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.