

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
74791665	JL038692
DATE 9/15/26	

MOTOR CARRIER OPERATOR E.R.T. TRANSPORTATION Services LLC	INSPECTOR'S NAME (PRINT OR TYPE) FRANK BAYDHER
ADDRESS PO Box 433	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE WILLIAMSPORT, MD, 21795	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) Ridge Runner Road Service

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM											
✓			a. Service Brakes	✓	X	9/16	a. Vehicle parts, load, dunnage, spare tire, etc., secured.				12. WINDSHIELD GLAZING
✓	X	9/16	b. Parking Brake System		X	9/16	b. Front End Structure	N/A			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	N/A			13. WINDSHIELD WIPERS
	X	9/16	d. Brake Hose								No missing, damaged, or inoperable wipers.
	N/A		e. Brake Tubing				7. STEERING MECHANISM				14. MOTORCOACH SEATS
			f. Low Pressure Warning Device				a. Steering Wheel Free Play	N/A			Seats securely fastened to the vehicle structure.
			g. Tractor Protection Valve				b. Steering Column				15. REAR IMPACT GUARD
			h. Air Compressor				c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
			i. Electric Brakes				d. Steering Gear Box				16. OTHER
			j. Hydraulic Brakes				e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
			k. Vacuum Systems				f. Power Steering				G37 G38
			l. Antilock Brake System				g. Ball and Socket Joints				(LFI) (LFO)
			m. Automatic Brake Adjusters				h. Tie Rods and Drag Links				G35 G36
							i. Nuts				
2. COUPLING DEVICES											
			a. Fifth Wheels				j. Steering System				
	N/A		b. Pintle Hooks				8. SUSPENSION				
			c. Drawbar/Towbar Eye		X	9/16	a. Axle Positioning Parts				
			d. Drawbar/Towbar Tongue				b. Spring Assembly				
			e. Safety Devices				c. Torque, Radius or Tracking Components				
			f. Saddle-Mounts				9. FRAME				
3. EXHAUST SYSTEM											
			a. No leaks forward of/ directly below the driver/sleeper compartment.				a. Frame Members				
	N/A		b. Bus: No leaking/ discharging in violation of standard.				b. Tire and Wheel Clearance				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				c. Adjustable Axle Assemblies (Sliding Subframes)				
4. FUEL SYSTEM											
			a. No visible leak.				10. TIRES				
			b. Fuel Tank Filler Cap		X	9/16	a. Steer-Axle Tires				
			c. Fuel tank securely attached.		N/A		b. All Other Tires				
5. LIGHTING DEVICES											
			All required lights/reflectors operable.				c. Speed-Restricted Tires				
							11. WHEELS AND RIMS				
							a. Lock or Side Ring				
							b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.