

**Bowman Leasing Columbus**

International
Columbus, OH 43228
ap@bowmanleasing.com, aepling@bowmanleasing.com
A0902

Imperial Freight Management LLC

6925 Urbana Road
Springfield, OH 45502
service@imperialexpress.net

Annual Vehicle Inspection Report - Trailer Only**Completed Date:** 9/3/2026**Unit:** 112242 **VIN:** 3H3V532C6JR112242**Year/Make/Model:** 2018 Hyundai Translead Hyundai Translead Trailers**Chassis Miles:** 0 Miles (9/3/2026)**Next Due:** 9/3/2027; 4,500 Miles**Service Order:** SO-102774**Chassis:** 3H3V532C6JR112242 2018 Hyundai Translead Hyundai Translead Trailers

Procedure	Result
1. BRAKE SYSTEM: a. Service Brakes	Satisfactory
2. BRAKE SYSTEM: b. Parking Brake System	Satisfactory
3. BRAKE SYSTEM: c. Brake Drums and Rotors	Satisfactory
4. BRAKE SYSTEM: d. Brake Hose	Satisfactory
5. BRAKE SYSTEM: e. Brake Tubing	Satisfactory
6. BRAKE SYSTEM: f. Antilock Brake System(ABS)	Satisfactory
7. BRAKE SYSTEM: g. Automatic Brake Adjusters	Satisfactory
8. BRAKE SYSTEM: h. Airleaks	Satisfactory
9. LIGHTING DEVICES: All lighting devices and reflectors by Part 393 shall be operable.	Satisfactory
10. BODY: a. Door Operation/ Seals	Satisfactory
11. BODY: b. Side panel on fiberglass reinforced plywood trailers	Satisfactory
12. BODY: d. Conspicuity tape on top left and right of trailer	Satisfactory
13. BODY: c. Conspicuity tape on ICC bumper	Satisfactory
14. SAFE LOADING: a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	Satisfactory
15. SAFE LOADING: b. Protection against shifting cargo.	Satisfactory
16. SAFE LOADING: c. Container securement devices on intermodal equipment.	Satisfactory
17. SUSPENSION: a. Any U-bolt(s), spring hanger(s) or other axle positioning part(s) cracked, broken loose or missing resulting in shifting of an axle from its normal position.	Satisfactory
18. SUSPENSION: b. Spring Assembly/Airbags	Satisfactory
19. SUSPENSION: c. Torque, Radius, or Tracking Components	Satisfactory
20. TIRES: a. All tires	Satisfactory
21. TIRES: b. Installation of speed restricted tires unless specifically designated by motor carrier.	Satisfactory
22. WHEELS AND RIMS: a. Lock or Side Ring	Satisfactory
23. WHEELS AND RIMS: b. Wheels and Rims	Satisfactory
24. WHEELS AND RIMS: c. Fasteners	Satisfactory
25. WHEELS AND RIMS: d. Welds	Satisfactory
26. WHEELS AND RIMS: e. Hubs	Satisfactory
27. WHEELS AND RIMS: f. Hub Oil	Satisfactory
28. FRAME: a. Frame Members	Satisfactory

29. FRAME: b. Tire and Wheel Clearance	Satisfactory
30. FRAME: c. Adjustable Axle Assemblies (Sliding Subframes)	Satisfactory
31. KING PIN: a. Check for Wear	Satisfactory
32. KING PIN: b. Cracks on King Pin	Satisfactory
33. TIRE MEASUREMENTS: Left Front Outside(LFO)	Satisfactory (10)
34. TIRE MEASUREMENTS: Left Front Inside(LFI)	Satisfactory (10)
35. TIRE MEASUREMENTS: Left Rear Outside(LRO)	Satisfactory (14)
36. TIRE MEASUREMENTS: Left Rear Inside(LRI)	Satisfactory (11)
37. TIRE MEASUREMENTS: Right Front Outside(RFO)	Satisfactory (6)
38. TIRE MEASUREMENTS: Right Front Inside(RFI)	Satisfactory (8)
39. TIRE MEASUREMENTS: Right Rear Inside(RRI)	Satisfactory (9)
40. TIRE MEASUREMENTS: Right Rear Outside(RRO)	Satisfactory (10)
41. BRAKE MEASUREMENTS: Left Front(LF)	Satisfactory (16)
42. BRAKE MEASUREMENTS: Left Rear(LR)	Satisfactory (16)
43. BRAKE MEASUREMENTS: Right Front(RF)	Satisfactory (16)
44. BRAKE MEASUREMENTS: Right Rear(RR)	Satisfactory (16)
45. Comments:	Satisfactory
46. CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.	Completed

Technician: William Muterspaw

Digital Signature: William Muterspaw

Date: 9/3/2026