

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

73116626

KL113345

DATE

9/17/26

MOTOR CARRIER OPERATOR

ERJ TRANSPORTATION SER. LLC

ADDRESS

PO BOX 433

CITY, STATE, ZIP CODE

WILLIAMSPORT, MARYLAND, 21795

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

FRANK BAUGHER

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

1JJVS32D3KL113345

INSPECTION AGENCY/LOCATION (OPTIONAL)

RIDGERUNNER ROAD SERVICE

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING			
	X	9/17	a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
	✓		b. Parking Brake System				b. Front End Structure				13. WINDSHIELD WIPERS
	X	9/17	c. Brake Drums or Rotors				c. Intermodal Container Securement Devices				No missing, damaged, or inoperable wipers.
	✓		d. Brake Hose								14. MOTORCOACH SEATS
	✓		e. Brake Tubing								Seats securely fastened to the vehicle structure.
	N/A		f. Low Pressure Warning Device								15. REAR IMPACT GUARD
			g. Tractor Protection Valve								In place, securely attached, proper size, proper placement (see 393.86).
			h. Air Compressor								16. OTHER
			i. Electric Brakes								List any other condition(s) which may prevent safe operation of this vehicle.
			j. Hydraulic Brakes								G42
			k. Vacuum Systems								G43
			l. Antilock Brake System								G44
			m. Automatic Brake Adjusters								G45
2. COUPLING DEVICES				7. STEERING MECHANISM							
	✓		a. Fifth Wheels				a. Steering Wheel Free Play				
	N/A		b. Pintle Hooks				b. Steering Column				
			c. Drawbar/Towbar Eye				c. Front Axle Beam/All Other Steering Components				
			d. Drawbar/Towbar Tongue				d. Steering Gear Box				
			e. Safety Devices				e. Pitman Arm				
			f. Saddle-Mounts				f. Power Steering				
3. EXHAUST SYSTEM				8. SUSPENSION							
	N/A		a. No leaks forward of/ directly below the driver/sleeper compartment.				a. Axle Positioning Parts				
			b. Bus: No leaking/ discharging in violation of standard.				b. Spring Assembly				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				c. Torque, Radius or Tracking Components				
4. FUEL SYSTEM				9. FRAME							
	N/A		a. No visible leak.				a. Frame Members				
			b. Fuel Tank Filler Cap				b. Tire and Wheel Clearance				
			c. Fuel tank securely attached.				c. Adjustable Axle Assemblies (Sliding Subframes)				
5. LIGHTING DEVICES				10. TIRES							
	✓		All required lights/reflectors operable.				a. Steer-Axle Tires				
							b. All Other Tires				
							c. Speed-Restricted Tires				
				11. WHEELS AND RIMS							
							a. Lock or Side Ring				
							b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.