

ANNUAL VEHICLE INSPECTION REPORT

9/8 | 9/12
9/9 | 9/12

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
	HR210738	9-10-26

MOTOR CARRIER OPERATOR <i>Bowman</i>	INSPECTOR'S NAME (PRINT OR TYPE) <i>Orlando</i>
ADDRESS <i>24254 Riverside Dr.</i>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE <i>Channahon IL</i>	VEHICLE IDENTIFICATION (VAND COMPLETE) ☒ LIC. PLATE NO. <i>4831338</i> ☐ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				e. Pitman Arm
☒			a. Service Brakes	☒			f. Power Steering
☒			b. Parking Brake System	☒			g. Ball and Socket Joints
☒			c. Brake Drums or Rotors	☒			h. Tie Rods and Drag Links
☒			d. Brake Hose	☒			i. Nuts
☒			e. Brake Tubing	☒			j. Steering System
☒			f. Low Pressure Warning Device	☒			8. SUSPENSION
☒			g. Tractor Protection Valve	☒			a. Axle Positioning Parts
☒			h. Air Compressor	☒			b. Spring Assembly
☒			i. Electric Brakes	☒			c. Torque, Radius or Tracking Components
☒			j. Hydraulic Brakes	☒			9. FRAME
☒			k. Vacuum Systems	☒			a. Frame Members
☒			l. Antilock Brake System	☒			b. Tire and Wheel Clearance
☒			m. Automatic Brake Adjusters	☒			c. Adjustable Axle Assemblies (Sliding Subframes)
☒			2. COUPLING DEVICES	☒			10. TIRES
☒			a. Fifth Wheels	☒			a. Steer-Axle Tires
☒			b. Pintle Hooks	☒			b. All Other Tires
☒			c. Drawbar/Towbar Eye	☒			c. Speed-Restricted Tires
☒			d. Drawbar/Towbar Tongue	☒			11. WHEELS AND RIMS
☒			e. Safety Devices	☒			a. Lock or Side Ring
☒			f. Saddle-Mounts	☒			b. Wheels and Rims
☒			3. EXHAUST SYSTEM	☒			c. Fasteners
☒			a. No leaks forward of/directly below the driver/sleeper compartment.	☒			d. Welds
☒			b. Bus: No leaking/discharging in violation of standard.	☒			12. WINDSHIELD GLAZING
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			4. FUEL SYSTEM	☒			13. WINDSHIELD WIPERS
☒			a. No visible leak.	☒			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
☒			b. Fuel Tank Filler Cap	☒			14. MOTORCOACH SEATS
☒			c. Fuel tank securely attached.	☒			Any passenger seat that is not securely fastened to the vehicle structure.
☒			5. LIGHTING DEVICES	☒			15. REAR IMPACT GUARD
☒			All lighting devices and reflectors required by Section 393 shall be operable.	☒			In place, securely attached, proper size, proper placement (see 393.86).
☒			6. SAFE LOADING	☒			16. OTHER
☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			List any other condition(s) which may prevent safe operation of this vehicle.
☒			b. Front End Structure	☒			
☒			c. Intermodal Container Securement Devices	☒			
☒			7. STEERING MECHANISM	☒			
☒			a. Steering Wheel Free Play	☒			
☒			b. Steering Column	☒			
☒			c. Front Axle Beam/All Other Steering Components	☒			
☒			d. Steering Gear Box	☒			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.