

Tires

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

DATE

KR 993008
9-16-2026

MOTOR CARRIER OPERATOR

Bowman Trailer Leasing

ADDRESS

24254 Riverside Drive

CITY, STATE, ZIP CODE

Channahon, IL 60410

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS
☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

John Hickman

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

YES

VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☒ OTHER

INSPECTION AGENCY/LOCATION (OPTIONAL)

JSH Mobile Service LLC

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System	☒			b. Front End Structure	☒			13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors	☒			c. Intermodal Container Securement Devices	☒			No missing, damaged, or inoperable wipers.
☒			d. Brake Hose	☒				☒			14. MOTORCOACH SEATS
☒			e. Brake Tubing	☒				☒			Seats securely fastened to the vehicle structure.
☒			f. Low Pressure Warning Device	☒				☒			15. REAR IMPACT GUARD
☒			NA	☒			7. STEERING MECHANISM	☒			In place, securely attached, proper size, proper placement (see 393.86).
☒			NA	☒			a. Steering Wheel Free Play	☒			16. OTHER
☒			NA	☒			b. Steering Column	☒			List any other condition(s) which may prevent safe operation of this vehicle.
☒			NA	☒			c. Front Axle Beam/All Other Steering Components	☒			Has GPS
☒			NA	☒			d. Steering Gear Box	☒			
☒			NA	☒			e. Pitman Arm	☒			
☒			NA	☒			f. Power Steering	☒			
☒			NA	☒			g. Ball and Socket Joints	☒			
☒			NA	☒			h. Tie Rods and Drag Links	☒			
☒			NA	☒			i. Nuts	☒			
☒			NA	☒			j. Steering System	☒			
			2. COUPLING DEVICES				8. SUSPENSION				
☒			a. Fifth Wheels	☒			a. Axle Positioning Parts	☒			
☒			b. Pintle Hooks	☒			b. Spring Assembly	☒			
☒			c. Drawbar/Towbar Eye	☒			c. Torque, Radius or Tracking Components	☒			
☒			d. Drawbar/Towbar Tongue	☒				☒			
☒			e. Safety Devices	☒			9. FRAME	☒			
☒			f. Saddle-Mounts	☒			a. Frame Members	☒			
			3. EXHAUST SYSTEM				b. Tire and Wheel Clearance	☒			
☒			a. No leaks forward of/ directly below the driver/sleeper compartment.	☒			c. Adjustable Axle Assemblies (Sliding Subframes)	☒			
☒			b. Bus: No leaking/ discharging in violation of standard.	☒				☒			
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒			10. TIRES	☒			
			4. FUEL SYSTEM				a. Steer-Axle Tires	☒			
☒			a. No visible leak.	☒			b. All Other Tires	☒			
☒			b. Fuel Tank Filler Cap	☒			c. Speed-Restricted Tires	☒			
☒			c. Fuel tank securely attached.	☒			11. WHEELS AND RIMS	☒			
			5. LIGHTING DEVICES				a. Lock or Side Ring	☒			
☒			All required lights/reflectors operable.	☒			b. Wheels and Rims	☒			
☒				☒			c. Fasteners	☒			
☒				☒			d. Welds	☒			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.