

Equipment ID CR165794 VIN CR165794 Year 2019 Manufacturer Hyundai Primary Plate

DOT / BIT Inspection and PMI Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

☒ Glad Hands & Rubber Grommets	☐ Repaired	☒ Aerodynamic Side Skirts	☐ Repaired
☒ 7-Way Electrical Plug	☐ Repaired	☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	☐ Repaired
☒ Registration, Valid License Plate and Sticker	☐ Repaired	☒ Lubricant Level in each Wheel End - Fill if necessary	☐ Repaired
☒ Lights, Wiring and Splice Conditions	☐ Repaired	☒ Wheels - Check for Cracks / Tire Matching	☐ Repaired
☒ Exterior Trailer - Body Condition and Coupling Device	☐ Repaired	☒ Tires - Free of Impermissible damage or wear	☐ Repaired
☒ Corner Locking Devices	☐ Repaired	☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	☐ Repaired
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	☐ Repaired	☒ Metal Flow-Thru Valve Stem Caps	☐ Repaired
☒ Fuel Tank and Fuel System (Reefer)	☐ Repaired	☒ Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	☐ Repaired
☒ Air Brake System - Test for Leaks	☐ Repaired	☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard	☐ Repaired
☒ Dump Valve (Air Ride Only) - Test operation and check for Leaks	☐ Repaired	☒ Doors - Proper Operation	☐ Repaired
☒ ABS System - Activate	☐ Repaired	☒ Door Hold Backs and Pull Handles - Present & Functional	☐ Repaired
☒ Air Lines - Check for damage / wear / chaffing	☐ Repaired	☒ All Hinges, Rollers, Locks - Lubricate	☐ Repaired
☒ Suspension Hangers - Free of defects and cracks	☐ Repaired	☒ Interior Trailer - Floor, Roof, and Side Walls	☐ Repaired
☒ Air Tank and Mounting Brackets	☐ Repaired	☒ Interior - Resecure Plywood as Needed	☐ Repaired
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	☐ Repaired	☒ DOT Inspected - Sticker Applied	☐ Repaired
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	☐ Repaired	☒ California BIT Inspected & Passed	☐ Repaired
☒ Suspension / U-Bolts / Springs - Free of defects and cracks	☐ Repaired		
☒ Flatbed Winches - Lubricate and Cycle	☐ Repaired		
☒ Sub-Frame - Free of Cracks / Bent Crossmembers	☐ Repaired		

NOTES:

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	10		100	RO Front	10		100
	LI Front	10		100	RI Front	10		100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	10		100	RO Rear	10		100
	LI Rear	10		100	RI Rear	10		100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	9/8
	R Front	
2	L Middle	
	R Middle	
3	L Rear	9/8
	R Rear	

Hubb: _____
 Engine Hrs: _____
 Prot. Timer: _____
 Fuel (lbs): _____

By signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 395.67, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 395.37.

Inspection Conducted By: Gary McDonald (Inspector Signature)

Inspection Date: 9-14-26

Print Name: Gary McDonald Company Name: Dedicated Fleet Services, LLC