

ANNUAL VEHICLE INSPECTION REPORT

112853

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	MM106531
DATE	9-18-26

MOTOR CARRIER OPERATOR Bowman Leasing	INSPECTOR'S NAME (PRINT OR TYPE) Paul Scott
ADDRESS PO Box 433	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Williamsport, MD 21795	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER 5VEV532C7MM06531
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
☒			a. Service Brakes
☒			b. Parking Brake System
☒			c. Brake Drums or Rotors
☒			d. Brake Hose
☒			e. Brake Tubing
☒			f. Low Pressure Warning Device
☒			g. Tractor Protection Valve
☒			h. Air Compressor
☒			i. Electric Brakes
☒			j. Hydraulic Brakes
☒			k. Vacuum Systems
2. COUPLING DEVICES			
☒			a. Fifth Wheels
☒			b. Pintle Hooks
☒			c. Drawbar/Towbar Eye
☒			d. Drawbar/Towbar Tongue
☒			e. Safety Devices
☒			f. Saddle-Mounts
3. EXHAUST SYSTEM			
☒			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.
☒			b. Bus exhaust system leaking or discharging in violation of standard.
☒			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.
4. FUEL SYSTEM			
☒			a. Visible leak.
☒			b. Fuel tank filler cap missing.
☒			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
☒			All lighting devices and reflectors required by Part 393 shall be operable.
6. SAFE LOADING			
☒			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
☒			b. Protection against shifting cargo.
☒			c. Container securement devices on intermodal equipment.
7. STEERING MECHANISM			
☒			a. Steering Wheel Free Play
☒			b. Steering Column
☒			c. Front Axle Beam and All Steering Components Other Than Steering Column
☒			d. Steering Gear Box
☒			e. Pitman Arm
☒			f. Power Steering
☒			g. Ball and Socket Joints
☒			h. Tie Rods and Drag Links
☒			i. Nuts
☒			j. Steering System
8. SUSPENSION			
☒			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
☒			b. Spring Assembly
☒			c. Torque, Radius or Tracking Components
9. FRAME			
☒			a. Frame Members
☒			b. Tire and Wheel Clearance
☒			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
☒			a. Tires on any steering axle of a power unit.
☒			b. All other tires.
11. WHEELS AND RIMS			
☒			a. Lock or Side Ring
☒			b. Wheels and Rims
☒			c. Fasteners
☒			d. Welds
12. WINDSHIELD GLAZING			
☒			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
13. WINDSHIELD WIPERS			
☒			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
14. OTHER			
☒			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK ☐ NEEDS REPAIR ☐ IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION II ACCORDANCE WITH 49 CFR PART 396.