

Equipment ID	VIN	Year	Manufacturer	Primary Plate
MR747226	3H3V53ACXMR947226	CU		140657T

DOT / BIT Inspection and PM Worksheet

☒ Glad Hands & Rubber Grommets	Check Mark = OK	X = Needs Further Attention	R = Repaired	N/A = Not Applicable
☒ 7-Way Electrical Plug		Repaired ☐	☒ Aerodynamic Side Skirts	Repaired ☐
☒ Registration, Valid License Plate and sticker		Repaired ☐	☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	Repaired ☐
☒ Lights, Wiring and Splice Conditions		Repaired ☐	☒ Lubricant Level in each Wheel End - Fill if necessary	Repaired ☐
☒ Exterior Trailer - Body Condition and Coupling Device		Repaired ☐	☒ Wheels - Check for Cracks / Tire Matching	Repaired ☐
☒ Corner Locking Devices		Repaired ☐	☒ Tires - free of impermissible damage or wear	Repaired ☐
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle		Repaired ☐	☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	Repaired ☐
☒ Fuel Tank and Fuel System (Reefer)		Repaired ☐	☒ Metal Flow-Thru Valve Stem Caps	Repaired ☐
☒ Air Brake System - Test for Leaks		Repaired ☐	☒ Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	Repaired ☐
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks		Repaired ☐	☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard	Repaired ☐
☒ ABS System - Actuate		Repaired ☐	☒ Doors - Proper Operation	Repaired ☐
☒ Air Lines - Check for damage / wear / chaffing		Repaired ☐	☒ Door Hold Backs and Pull Handles - Present & Functional	Repaired ☐
☒ Suspension Hangers - Free of defects and cracks		Repaired ☐	☒ All Hinges, Rollers, locks - Lubricate	Repaired ☐
☒ Air Tank and Mounting Brackets		Repaired ☐	☒ Interior Trailer - Floor, Roof, and Side Walls	Repaired ☐
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks		Repaired ☐	☒ Interior - Resecure Plywood as Needed	Repaired ☐
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust		Repaired ☐	☒ DOT Inspected - Sticker Applied	Repaired ☐
☒ Suspension / U-Bolts / Springs - Free of defects and cracks		Repaired ☐	☒ California BIT Inspected & Passed	Repaired ☐
☒ Flatbed Winches - Lubricate and Cycle		Repaired ☐		
☒ Sub-Frame - Free of Cracks / Bent Crossmembers		Repaired ☐		

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	12	FS	100	RO Front	13	FS	100
	LI Front	12	FS	100	RI Front	13	FS	100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	12	DR	100	RO Rear	10	FS	100
	LI Rear	12	DR	100	RI Rear	10	FS	100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	7
	R Front	7
2	L Middle	
	R Middle	
3	L Rear	7
	R Rear	7

Hubo: 6

Engine Hrs: _____

Prot. Time: _____

Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By:

(Inspector Signature)

Print Name:

Charles Santos

Company Name:

RSS Trailer Repair

Inspection Date:

9/11/2026