

Equipment ID VIN Year Manufacturer Primary Plate
748057-3H3V532C7MR748057-11/20-Hyundai-141238T

DOT / BIT Inspection and PM Worksheet

☒	Glad Hands & Rubber Grommets	Check Mark = OK	X = Needs Further Attention	☐	Repaired
☒	7-Way Electrical Plug			☐	Repaired
☒	Registration, Valid License Plate and sticker			☐	Repaired
☒	Lights, Wiring and Splice Conditions			☐	Repaired
☒	Exterior Trailer - Body Condition and Coupling Device			☐	Repaired
☒	Corner Locking Devices			☐	Repaired
☒	Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle			☐	Repaired
☒	Fuel Tank and Fuel System (Reefer)			☐	Repaired
☒	Air Brake System - Test for Leaks			☐	Repaired
☒	Dump Valve (Air Ride Only) - Test operation and check for Leaks			☐	Repaired
☒	ABS System - Actuate			☐	Repaired
☒	Air Lines - Check for damage / wear / chaffing			☐	Repaired
☒	Suspension Hangers - Free of defects and cracks			☐	Repaired
☒	Air Tank and Mounting Brackets			☐	Repaired
☒	Brakes - Drums / Linings / Air Chambers - free of defects and cracks			☐	Repaired
☒	Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust			☐	Repaired
☒	Suspension / U-Bolts / Springs - Free of defects and cracks			☐	Repaired
☒	Flatbed Winches - Lubricate and Cycle			☐	Repaired
☒	Sub-Frame - Free of Cracks / Bent Crossmembers			☐	Repaired

☒	Aerodynamic Side Skirts	R = Repaired	N/A = Not Applicable	☐	Repaired
☒	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper			☐	Repaired
☒	Lubricant Level in each Wheel End - Fill if necessary			☐	Repaired
☒	Wheels - Check for Cracks / Tire Matching			☐	Repaired
☒	Tires - free of Impermissible damage or wear			☐	Repaired
☒	Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs			☐	Repaired
☒	Metal Flow-Thru Valve Stem Caps			☐	Repaired
☒	Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards			☐	Repaired
☒	Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard			☐	Repaired
☒	Doors - Proper Operation			☐	Repaired
☒	Door Hold Backs and Pull Handles - Present & Functional			☐	Repaired
☒	All Hinges, Rollers, Locks - Lubricate			☐	Repaired
☒	Interior Trailer - Floor, Roof, and Side Walls			☐	Repaired
☒	Interior - Resecure Plywood as Needed			☐	Repaired
☒	DOT Inspected - Sticker Applied			☐	Repaired
☐	California BIT Inspected & Passed			☐	Repaired

NOTES: _____

TIRES (in 32nds)					
Axle	Position	TD	Brand	PSI	Position
1	LO Front	14	HM	100	RO Front
	LI Front	14	HM	100	RI Front
2	LO Middle	14	HM	100	RO Middle
	LI Middle	14	HM	100	RI Middle
3	LO Rear	13	MI	100	RO Rear
	LI Rear	13	MI	100	RI Rear

Brakes (in 8ths)			
Axle	Position	Depth	Hubo: _____
1	L Front	10/10	Engine Hrs: _____
	R Front	9/10	
2	L Middle	10/10	Prot. Time: _____
	R Middle	10/10	
3	L Rear	10/10	Fuel 8ths: _____
	R Rear	10/10	

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By: _____ (Inspector's Signature)

Inspection Date: 9/17/2026

Print Name: _____

Company Name: _____
