

Equipment ID	VIN	Year	Manufacturer	Primary Plate
RC54137	15V8VC5327HT06700	2016	VALVED	5483981

DOT / BIT Inspection and PM Worksheet

☒ Glad Hands & Rubber Grommets	Check Mark = OK	☐ X = Needs Further Attention	☐ R = Repaired	☒ N/A = Not Applicable
☒ 7-Way Electrical Plug	Repaired ☐		☒ Aerodynamic Side Skirts	Repaired ☐
☒ Registration, Valid License Plate and sticker	Repaired ☐		☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	Repaired ☐
☒ Lights, Wiring and Splice Conditions	Repaired ☐		☒ Lubricant Level in each Wheel End - Fill if necessary	Repaired ☐
☒ Exterior Trailer - Body Condition and Coupling Device	Repaired ☐		☒ Wheels - Check for Cracks / Tire Matching	Repaired ☐
☐ Corner Locking Devices	Repaired ☐		☒ Tires - free of impermissible damage or wear	Repaired ☐
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	Repaired ☐		☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	Repaired ☐
☐ Fuel Tank and Fuel System (Reefer)	Repaired ☐		☒ Metal Flow-Thru Valve Stem Caps	Repaired ☐
☒ Air Brake System - Test for Leaks	Repaired ☐		☒ Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards	Repaired ☐
☒ Dump Valve (Air Ride Only) - Test operation and check for Leaks	Repaired ☐		☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard	Repaired ☐
☒ ABS System - Actuate	Repaired ☐		☒ Doors - Proper Operation	Repaired ☐
☒ Air Lines - Check for damage / wear / chaffing	Repaired ☐		☒ Door Hold Backs and Pull Handles - Present & Functional	Repaired ☐
☒ Suspension Hangers - Free of defects and cracks	Repaired ☐		☒ All Hinges, Rollers, Locks - Lubricate	Repaired ☐
☒ Air Tank and Mounting Brackets	Repaired ☐		☒ Interior Trailer - Floor, Roof, and Side Walls	Repaired ☐
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	Repaired ☐		☒ Interior - Resecure Plywood as Needed	Repaired ☐
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired ☐		☒ DOT Inspected - Sticker Applied	Repaired ☐
☒ Suspension / U-Bolts / Springs - Free of defects and cracks	Repaired ☐		☐ California BIT Inspected & Passed	Repaired ☐
☐ Flatbed Winches - Lubricate and Cycle	Repaired ☐			
☒ Sub-Frame - Free of Cracks / Bent Crossmembers	Repaired ☐			

NOTES:

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	10	BLUE	100	RO Front	10	BLUE	100
	LI Front	8	SVCT	100	RI Front	10	SVCT	100
2	LO Middle				RO Middle			
	LI Middle	8	SVCT	100	RI Middle			
	LO Rear				RO Rear			
3	LI Rear	10	SVCT	100	RI Rear	10	SVCT	100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	5
	R Front	5
2	L Middle	
	R Middle	
	L Rear	5
3	R Rear	5

Hubo: 110113

Engine Hrs: _____

Prot. Time: _____

Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By: _____
(Inspector Signature)

Inspection Date: 9/15/26

Print Name: CARLOS SANTI

Company Name: RSS Trailer Repair