

Equipment ID 5734061 VIN MB734061 Year 2016 Manufacturer Stoelke Primary Plate _____

DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

☒ Glad Hands & Rubber Grommets	Inspected ☐	☒ Aerodynamic Side Skirts	Repaired ☐
☒ 7-Way Electrical Plug	Inspected ☐	☒ Slider Mechanism & Locking Pins - Lubricate, Rotate, Re-engage Proper	Repaired ☐
☒ Registration, Valid License Plate and sticker	Inspected ☐	☒ Lubricant Level in each Wheel End - Fill if necessary	Repaired ☐
☒ Lights, Wiring and Splice Conditions	Inspected ☐	☒ Wheels - Check for Cracks / Tire Matching	Repaired ☐
☒ Exterior Trailer - Body Condition and Coupling Device	Inspected ☐	☒ Tires - free of impermissible damage or wear	Repaired ☐
☒ Corner Locking Devices	Inspected ☐	☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	Repaired ☐
☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle	Inspected ☐	☒ Metal Flow-Thru Valve Stem Caps	Repaired ☐
☒ Fuel Tank and Fuel System (Noiser)	Inspected ☐	☒ Conspectuity Tape - Slide Panels, Rear Doors, Rear Impact Guard, Headboards	Repaired ☐
☒ Air Brake System - Test for leaks	Inspected ☐	☒ Mudflaps, Brackets, Rubber Deck Bumpers, and Rear Impact Guard	Repaired ☐
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks	Inspected ☐	☒ Doors - Proper Operation	Repaired ☐
☒ ABS system - Actuate	Inspected ☐	☒ Door Hold Backs and Pull Handles - Present & Functional	Repaired ☐
☒ Air Lines - Check for damage / wear / chaffing	Inspected ☐	☒ All Hinges, Rollers, Leads - Lubricate	Repaired ☐
☒ Suspension Hangers - Free of defects and cracks	Inspected ☐	☒ Interior Trailer - Floor, Roof, and Side Walls	Repaired ☐
☒ Air Tank and Mounting Brackets	Inspected ☐	☒ Interior - Resecure Plywood as Needed	Repaired ☐
☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks	Inspected ☐	☒ DOT Inspected - Sticker Applied	Repaired ☐
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Inspected ☐	☒ California BIT Inspected & Passed	Repaired ☐
☒ Suspension / U-Bolts / Springs - Free of defects and cracks	Inspected ☐		
☒ Flatbed Winches - Lubricate and Cycle	Inspected ☐		
☒ Sub-Frame - Free of Cracks / Bent Crossmembers	Inspected ☐		

TIRES (in 32nds)

Axle	Position	TP	Brand	PSI	Position	TP	Brand	PSI
1	LO Front	11		100	RO Front	11		100
1	LI Front	11		100	RI Front	11		100
2	LO Middle				RO Middle			
2	LI Middle				RI Middle			
3	LO Rear	11		100	RO Rear	11		100
3	LI Rear	11		100	RI Rear	11		100

Brakes (in Bits)

Axle	Position	Depth	Huber
1	L Front	5/8"	Engine Hrs: _____
1	R Front	5/8"	Prod. Time: _____
2	L Middle		Fuel Bkts: _____
2	R Middle		
3	L Rear	3/4"	
3	R Rear	3/4"	

by signing and dating this form the Inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 395, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 395.27.

Inspection Conducted By: A. T. Phillip (Inspector Signature)

Print Name: TCOY Phillip Company Name: Dedicated Fleet Services, LLC

Inspection Date: 9-3-26