

Equipment ID VIN Year Manufacturer Primary Plate
TL644906-12JVS32DTL644906-06124-644063T

DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

☒ Glad Hands & Rubber Grommets ☐ Repaired

☒ 7-Way Electrical Plug ☐ Repaired

☒ Registration, Valid License Plate and sticker ☐ Repaired

☒ Lights, Wiring and Splice Conditions ☐ Repaired

☒ Exterior Trailer - Body Condition and Coupling Device ☐ Repaired

☒ Corner Locking Devices ☐ Repaired

☒ Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle ☐ Repaired

☒ Fuel Tank and Fuel System (Reefer) ☐ Repaired

☒ Air Brake System - Test for Leaks ☐ Repaired

☒ Dump Valve (Air Ride Only) - Test operation and check for Leaks ☐ Repaired

☒ ABS System - Actuate ☐ Repaired

☒ Air Lines - Check for damage / wear / chaffing ☐ Repaired

☒ Suspension Hangers - Free of defects and cracks ☐ Repaired

☒ Air Tank and Mounting Brackets ☐ Repaired

☒ Brakes - Drums / Linings / Air Chambers - free of defects and cracks ☐ Repaired

☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust ☐ Repaired

☒ Suspension / U-Bolts / Springs - Free of defects and cracks ☐ Repaired

☒ Flashed Winches - Lubricate and Cycle ☐ Repaired

☒ Sub-Frame - Free of Cracks / Bent Crossmembers ☐ Repaired

☒ Aerodynamic Side Skirts ☐ Repaired

☒ Slider Mechanism & Locking Pins - lubricate, Release, Re-engage Proper ☐ Repaired

☒ Lubricant Level in each Wheel End - Fill if necessary ☐ Repaired

☒ Wheels - Check for Cracks / Tire Matching ☐ Repaired

☒ Tires - Free of impermissible damage or wear ☐ Repaired

☒ Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs ☐ Repaired

☒ Metal Flow-Thru Valve Stem Caps ☐ Repaired

☒ Consistency Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards ☐ Repaired

☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard ☐ Repaired

☒ Doors - Proper Operation ☐ Repaired

☒ Door Hold Backs and Pull Handles - Present & Functional ☐ Repaired

☒ All Hinges, Rollers, Locks - Lubricate ☐ Repaired

☒ Interior Trailer - Floor, Roof, and Side Walls ☐ Repaired

☒ Interior - Resecure Plywood as Needed ☐ Repaired

☒ DOT Inspected - Sticker Applied ☐ Repaired

☒ California BIT Inspected & Passed ☐ Repaired

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	11	YH	100	RO Front	10	YH	100
	LI Front	11	YH	100	RI Front	10	YH	100
2	LO Middle	11	YH	100	RO Middle	11	YH	100
	LI Middle	11	YH	100	RI Middle	11	YH	100
3	LO Rear	9	HR	100	RO Rear	10	1M	100
	LI Rear	9	HR	100	RI Rear	10	1M	100

Brakes (in 8ths)

Axle	Position	Depth
1	L Front	10/10
	R Front	10/10
2	L Middle	11
	R Middle	11
3	L Rear	10/10
	R Rear	10/10

Hubo: C

Engine Hrs: _____

Prot. Time: _____

Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection Conducted By: [Signature] (Inspector Signature)

Inspection Date: 9/11/2026

Print Name: David Ortiz Company Name: SS Trailer Repair