

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
72941229	TM601959
DATE	
09/11/26	

MOTOR CARRIER OPERATOR Bowman Trailer Leasing	INSPECTOR'S NAME (PRINT OR TYPE)
ADDRESS 24254 Riverside Dr	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Channahon IL 60410	VEHICLE IDENTIFICATION (✓) AND COMPLETE ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 5UBUC5322 TM601959
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			1. BRAKE SYSTEM	N/A			4. FUEL SYSTEM	✓			9. FRAME
✓			a. Service Brakes	N/A			a. Visible leak	✓			a. Frame Members
✓			b. Parking Brake System	N/A			b. Fuel tank filler cap missing	✓			b. Tire and Wheel Clearance
✓			c. Brake Drums or Rotors	N/A			c. Fuel tank securely attached	N/A			c. Adjustable Axle Assemblies (Sliding Subframes)
✓			d. Brake Hose								
✓			e. Brake Tubing	✓			5. LIGHTING DEVICES	✓			10. TIRES
N/A			f. Low Pressure Warning Device				All lighting devices and reflectors required by Section 393 shall be operable.	✓			a. Tires on any steering axle of a power unit.
N/A			g. Tractor Protection Valve					✓			b. All other tires.
N/A			h. Air Compressor	✓			6. SAFE LOADING	✓			11. WHEELS AND RIMS
N/A			i. Electric Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	✓			a. Lock or Side Ring
N/A			j. Hydraulic Brakes				b. Protection against shifting cargo	✓			b. Wheels and Rims
N/A			k. Vacuum Systems					✓			c. Fasteners
N/A								✓			d. Welds
N/A			2. COUPLING DEVICES	✓			7. STEERING MECHANISM	N/A			12. WINDSHIELD GLAZING
N/A			a. Fifth Wheels				a. Steering Wheel Free Play				Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions)
N/A			b. Pintle Hooks	N/A			b. Steering Column				
✓			c. Drawbar/Towbar Eye	N/A			c. Front Axle Beam and All Steering Components Other Than Steering Column				13. WINDSHIELD WIPERS
✓			d. Drawbar/Towbar Tongue	N/A							Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
✓			e. Safety Devices	N/A			d. Steering Gear Box				
✓			f. Saddle-Mounts	N/A			e. Pitman Arm				
N/A			3. EXHAUST SYSTEM				f. Power Steering				
			a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment.	N/A			g. Ball and Socket Joints				
				N/A			h. Tie Rods and Drag Links				
N/A			b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3).	N/A			i. Nuts				
				N/A			j. Steering System				
N/A			c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle.	N/A			8. SUSPENSION				
				N/A			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
				N/A			b. Spring Assembly				
							c. Torque, Radius or Tracking Components.				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, ✗ NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 49 CFR 396.