



FMCSA ANNUAL INSPECTION FORM

HYUNDAI TRANSLEAD

Plant: Playas de Rosarito, Baja California, MX. CP 22707

Rosarito B.C. México.

Corporate Office: 8880 Rio San Diego Drive, Ste # 600

San Diego, CA 92108

Inspection Facility: HT Rosarito Plant	Unit Number: VS092674	Hubodometer (if applicable): OK
City and State: Rosarito, Baja California, MX.	Customer: BOWMAN TRAILER LEASING	S.A.P. Number: 30024904
Inspector Name: Pablo Sanchez Flores	VIN Number: 3H3V532K2VS092674	License Plate Number: 841024T
Inspection Date: 09-02-2026 ☒ Pass ☐ Fail	Repair Date: N/A	Make: Hyundai
		Year / Model: 2027/VC2530152-JS

OK	NEEDS REPAIR	ITEMS INSPECTED	OK	NEEDS REPAIR	ITEMS INSPECTED
		BRAKE SYSTEM			SAFE LOADING
X		Service Brakes	X		Part(s) of vehicle or condition of loading such as spare tire or any part of the load or dunnage can fall onto the roadway
X		Parking Brake System			
X		Brake Drums or Rotors			
X		Brake Hose	N/A		Protection against shifting cargo
X		Brake Tubing			STEERING MECHANISM
X		Audible Air Leaks	N/A		For units with Steerable Rear Axle
		COUPLING DEVICES			SUSPENSION
X		Fifth Wheels / Upper Coupler	X		Any U Bolt(s), spring hanger(s) or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from it's normal position
N/A		Pintle Hooks			
N/A		Drawbar / Towbar Eye			
N/A		Drawbar / Towbar Tongue			
N/A		Safety Devices	X		Spring assembly
N/A		Saddle-Mounts	X		Torque, radius or tracking component
		EXHAUST SYSTEM / REFRIGERATED UNITS			FRAME
N/A		No part of the exhaust system of any motor vehicle shall be located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle	X		Frame members
			X		Tire and Wheel Clearance
			X		Adjustable Axle Assemblies (Sliding Sub-Frames)
			X		TIRES
		FUEL SYSTEM / REFRIGERATED UNITS	N/A		WHEELS AND RIMS
N/A		Visible leak	X		Lock or Side Ring
N/A		Fuel tank filler cap missing	X		Wheels and Rims
N/A		Fuel tank securely attached	X		Fasteners
		LIGHTING DEVICES	X		Welds
X		All lighting devices and reflectors required by Section 393 shall be operable.			REAR IMPACT GUARD
					SPLASH GUARDS
X		UNIT NUMBERS DISPLAYED	X		Driver Side
			X		Passenger Side

I have inspected the vehicle described above and certify that all entries are true and correct. I certify that this inspection meets the requirements of 49 CFR Part 396.17 and is in accordance with Appendix A to Subchapter B, Minimum Periodic Inspection Standards, and the vehicle has passed / failed as indicated above.

INSPECTOR'S NAME (Please Print): Pablo Sanchez Flores

INSPECTOR'S SIGNATURE: PabloFS