

Equipment ID: 275501 VIN: DK226637 Year: 2012 Manufacturer: Great Dane Primary Plate:
 DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention

☒ Glad Hands & Rubber Grommets	Repaired ☐
☒ 7-Way Electrical Plug	Repaired ☐
☒ Registration, Valid License Plate and Sticker	Repaired ☐
☒ Lights, Wiring and Splice Conditions	Repaired ☐
☒ Exterior Trailer - Body Condition and Coupling Device	Repaired ☐
☒ Corner Locking Devices	Repaired ☐
☒ Landing Gear Lugs / Gear Box and Bracing - Lubricate & Cycle	Repaired ☐
☒ Fuel Tank and Fuel System (If applicable)	Repaired ☐
☒ Air Brake System - Test for leaks	Repaired ☐
☒ Dump Valve (Air Ride Only) - Test operation and check for leaks	Repaired ☐
☒ ABS System - Actuate	Repaired ☐
☒ Air Lines - Check for damage / wear / chaffing	Repaired ☐
☒ Suspension Hangers - Free of defects and cracks	Repaired ☐
☒ Air Tank and Mounting Brackets	Repaired ☐
☒ Brakes - Drums / Linings / Air Chambers - Free of defects and cracks	Repaired ☐
☒ Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired ☐
☒ Suspension / U-Bolts / Springs - Free of defects and cracks	Repaired ☐
☒ Flatbed Winches - Lubricate and Cycle	Repaired ☐
☒ Sub-Frame - Free of Cracks / Bent Crossmembers	Repaired ☐

R = Repaired N/A = Not Applicable

☒ Aerodynamic Side Skirts	Repaired ☐
☒ Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Proper	Repaired ☐
☒ Lubricant Level in each Wheel End - Fill if necessary	Repaired ☐
☒ Wheels - Check for Cracks / Tire Matching	Repaired ☐
☒ Tires - Free of Impermissible damage or wear	Repaired ☐
☒ Lugnuts - Torque to 450-500 ft/lbs - Set Wrench to 500 ft/lbs	Repaired ☐
☒ Metal Flow-Thru Valve Stem Caps	Repaired ☐
☒ Conspicuously Tape - Slide Panels, Rear Doors, Rear Impact Guard, Headboards	Repaired ☐
☒ Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard	Repaired ☐
☒ Doors - Proper Operation	Repaired ☐
☒ Door Hold Backs and Pull Handles - Present & Functional	Repaired ☐
☒ All Hinges, Rollers, Locks - Lubricate	Repaired ☐
☒ Interior Trailer - Floor, Roof, and Side Walls	Repaired ☐
☒ Interior - Resecure Plywood as Needed	Repaired ☐
☒ DOT Inspected - Sticker Applied	Repaired ☐
☒ California BIT Inspected & Passed	Repaired ☐

NOTES:

Tires (in 32nds)

Axis	Position	ID	Brand	PSI	Position	ID	Brand	PSI
1	LO Front			100	RO Front			100
1	LI Front			100	RI Front			100
2	LO Middle			100	RO Middle			100
2	LI Middle			100	RI Middle			100
3	LO Rear			100	RO Rear			100
3	LI Rear			100	RI Rear			100

Brakes (in 8ths)

Axis	Position	Depth
1	L Front	2/8
1	R Front	
2	L Middle	
2	R Middle	
3	L Rear	5/8
3	R Rear	

Hubel: 29428 8
 Engine Hrs:
 Prod. Time:
 Fuel Bths:

By signing and dating this form the Inspector certifies (1) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396.17, and (2) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.12.

Inspection Conducted By: N. T. (Inspector Signature)
 Inspection Date: 9-11-26

Print Name: Troy Phillips Company Name: Dedicated Fleet Services, LLC