

INDIANA TRAILER SERVICE ANNUAL VEHICLE INSPECTION REPORT

1493 S 750 E
Lafayette, IN 47905

765-296-5621

FLEET UNIT NUMBER

154168

DATE

10/01/2026

MOTOR CARRIER OPERATOR	
Bowman Trailer Leasing	
ADDRESS	
10233 Governor Lane Blvd	
CITY	STATE, ZIP CODE
Williamsport, MD	21795
VEHICLE TYPE	TRACTOR ☒ TRAILER
HUBO	READING

INSPECTOR'S NAME	
ERIC CLEVINGER	
THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19	
☒ YES	
VEHICLE IDENTIFICATION	LIC PLATE VIN ☒ UNIT
	154168
INSPECTION LOCATION	
INDIANA TRAILER SERVICE	

OK	NEEDS REPAIR	DATE REPAIR	ITEM	OK	NEEDS REPAIR	DATE REPAIR	ITEM	OK	NEEDS REPAIR	DATE REPAIR	ITEM
1 BRAKE SYSTEM				6 SAFE LOADING				10 TIRES			
OK			A Service Brakes				A Parts of vehicle or condition of loading such that the spare tire or any part of load or dunnage can fall onto roadway.				A Tires on any steering axle of a power unit.
OK			B Parking Brake System	OK				OK			B All other tires.
OK			C Brake Drums or Rotors								
OK			D Brake Hose								
OK			E Brake Tubing								
NA			F Low Pressure Warning Device	NA			B Protection against shifting cargo.				11 WHEELS AND RIMS
NA			G Tractor protection Valve				C Container securement devices on intermodal equipment.	OK			A Lock or Slide Ring
NA			H Air Compressor	NA				OK			B Wheels and Rims
NA			I Electric Brakes					OK			C Fasteners
NA			J Hydraulic Brakes					OK			D Welds
NA			K Vacuum Systems								12 WINDSHIELD
2 COUPLING DEVICES				7 STEERING MECHANISM				13 WINDSHIELD WIPERS			
OK			A Fifth Wheels	NA			A Steering wheel freeplay	NA			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
NA			B Pintle Hooks				B Steering Column				
NA			C Drawbar/Towbar Eye	NA			C Front Axle Beam and all Steering Components Other than Steering Column				
NA			D Drawbar/Towbar Tongue				D Steering Gear Box				
NA			E Safety Devices	NA			E Pitman Arm				
NA			F Saddle-Mounts	NA			F Power Steering				
3 EXHAUST SYSTEM				8 SUSPENSION				14 OTHER			
			A Exhaust system leaking forward of or directly below the driver/sleeper compartment.				A Any U-bolt, spring hangers, or other axle positioning parts cracked broken, loose, or missing resulting in shifting of an axle from its normal positioning.				List any other conditions which may prevent safe operation of this vehicle.
NA							B Spring Assembly				
			B Bus exhaust system leaking or discharging in violation of standard.				C Torque, Radius or Tracking Componets				
			C Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	OK							
NA											
4 FUEL SYSTEM				9 FRAME							
NA			A Visable fuel leak.	OK			A Frame members				
NA			B Fuel tank cap missing.	OK			B Tire and Wheel clearance				
NA			C Fuel tank securely attached				C Adjustable Axle assemblies (sliding subframes).				
5 LIGHTING DEVICES											
OK			All lighting devices and reflectors required by 393 shall be operable.	OK							
				OK							

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396