

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD			
REPORT NUMBER	FLEET UNIT NUMBER	DATE	
101626A	JL038757	10/16/2026	
MOTOR CARRIER OPERATOR Bowman Trailer Leasing		INSPECTOR'S NAME (PRINT OR TYPE) S. Winkler	
ADDRESS 2395 Rossville Blvd.		THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19 ☒ YES	
CITY, STATE, ZIP CODE Chattanooga TN 37428		VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO ☒ VIN ☐ OTHER 1J5V532D3JL038757	
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ OTHER		INSPECTION AGENCY/LOCATION (OPTIONAL)	
VEHICLE COMPONENTS INSPECTED			
INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, ✗ NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hoses
✓			e. Brake Tubing
NA			f. Low Pressure Warning Device
NA			g. Tractor Protection Valve
NA			h. Air Compressor
NA			i. Electric Brakes
NA			j. Hydraulic Brakes
NA			k. Vacuum Systems
NA			l. Antilock Brake System
NA			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
✓			a. Fifth Wheels
NA			b. Pintle Hooks
NA			c. Drawbar/Towbar Eye
NA			d. Drawbar/Towbar Tongue
NA			e. Safety Devices
NA			f. Saddle-Mounts
3. EXHAUST SYSTEM			
NA			a. No leaks forward of/directly below the driver/sleeper compartment.
NA			b. Bus: No leaking/discharging in violation of standard.
NA			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
NA			a. No visible leak.
NA			b. Fuel Tank Filler Cap
NA			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
✓			All required lights/reflectors operable.
6. SAFE LOADING			
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
NA			b. Front End Structure
NA			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
NA			a. Steering Wheel Free Play
NA			b. Steering Column
NA			c. Front Axle Beam/All Other Steering Components
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
NA			d. Steering Gear Box
NA			e. Pitman Arm
NA			f. Power Steering
NA			g. Ball and Socket Joints
NA			h. Tie Rods and Drag Links
NA			i. Nuts
NA			j. Steering System
8. SUSPENSION			
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
9. FRAME			
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
NA			a. Steer-Axle Tires
✓			b. All Other Tires
NA			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
NA			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds
12. WINDSHIELD GLAZING			
NA			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
13. WINDSHIELD WIPERS			
NA			No missing, damaged, or inoperable wipers.
14. MOTORCOACH SEATS			
NA			Seats securely fastened to the vehicle structure.
15. REAR IMPACT GUARD			
✓			In place, securely attached, proper size, proper placement (see 393.86)
16. OTHER			
			List any other condition(s) which may prevent safe operation of this vehicle.

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

ORIGINAL