ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
	112242

DATE 7/14/26

MOTOR CARRIER OPERATOR: Bowman	INSPECTOR'S NAME (PRINT OR TYPE): R. Spaulding
ADDRESS: 112 Metrogate CT.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☐ YES
CITY, STATE, ZIP CODE: Simpsonville, SC, 29681	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER: 112242
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL): Pro Service

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
OK			a. Service Brakes
			b. Parking Brake System
			c. Brake Drums or Rotors
			d. Brake Hose
			e. Brake Tubing
NA			f. Low Pressure Warning Device
			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
OK			l. Antilock Brake System
			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
NA			a. Fifth Wheels
			b. Pintle Hooks
			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
			e. Safety Devices
			f. Saddle-Mounts
3. EXHAUST SYSTEM			
NA			a. No leaks forward of/ directly below the driver/ sleeper compartment.
			b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
NA			a. No visible leak.
			b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
OK			All required lights/reflectors operable.
6. SAFE LOADING			
OK			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
			b. Front End Structure
NA			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
NA			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
8. SUSPENSION			
OK			a. Axle Positioning Parts
			b. Spring Assembly
			c. Torque, Radius or Tracking Components
9. FRAME			
OK			a. Frame Members
			b. Tire and Wheel Clearance
			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
NA			a. Steer-Axle Tires
OK			b. All Other Tires
			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
NA			a. Lock or Side Ring
OK			b. Wheels and Rims
			c. Fasteners
			d. Welds
12. WINDSHIELD GLAZING			
NA			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
13. WINDSHIELD WIPERS			
NA			No missing, damaged, or inoperable wipers.
14. MOTORCOACH SEATS			
NA			Seats securely fastened to the vehicle structure.
15. REAR IMPACT GUARD			
OK			In place, securely attached, proper size, proper placement (see 393.86).
16. OTHER			
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL