ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	GT003277
DATE 11/5/26	

MOTOR CARRIER OPERATOR: Bowman

ADDRESS: 112 Metrogate Ct

CITY, STATE, ZIP CODE: Simpsonville SC 29681

VEHICLE TYPE: ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE): C. Spearman

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.: ☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☒ OTHER: GT003277

INSPECTION AGENCY/LOCATION (OPTIONAL): Pro Svc

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
NO			f. Low Pressure Warning Device
			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
NA			a. Fifth Wheels
			b. Pintle Hooks
			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
			e. Safety Devices
			f. Saddle-Mounts
			3. EXHAUST SYSTEM
			a. No leaks forward of/ directly below the driver/ sleeper compartment.
			b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
			4. FUEL SYSTEM
			a. No visible leak.
			b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			6. SAFE LOADING
			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
✓			c. Intermodal Container Securement Devices
NO			**7. STEERING MECHANISM**
			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
✓			j. Steering System
			8. SUSPENSION
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
NO			a. Steer-Axle Tires
✓			b. All Other Tires
✓			c. Speed-Restricted Tires
			11. WHEELS AND RIMS
NO			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			12. WINDSHIELD GLAZING
NO			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL