ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	HT368720
DATE 11-6-26	

MOTOR CARRIER OPERATOR: Bowman trailer Leasing
ADDRESS: 2395 Rossville Blvd
CITY, STATE, ZIP CODE: Chattanooga, TN 37408
VEHICLE TYPE: ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE): Wayne Brendel
THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER: 3H3V532C6MT368720
INSPECTION AGENCY/LOCATION (OPTIONAL): Chattanooga TN

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
			f. Low Pressure Warning Device
NA			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
NA			*j. Hydraulic Brakes*
			k. Vacuum Systems
			l. Antilock Brake System
			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
✓			a. Fifth Wheels PTN
NA			b. Pintle Hooks
			c. Drawbar/Towbar Eye
NA			d. Drawbar/Towbar Tongue
			e. Safety Devices
			f. Saddle-Mounts
			3. EXHAUST SYSTEM
NA			a. No leaks forward of/ directly below the driver/ sleeper compartment.
			b. Bus: No leaking/ discharging in violation of standard.
NA			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
			4. FUEL SYSTEM
NA			a. No visible leak.
			b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			6. SAFE LOADING
NA			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
			b. Front End Structure
NA			c. Intermodal Container Securement Devices
			7. STEERING MECHANISM
NA			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
			d. Steering Gear Box
NA			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
NA			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
			8. SUSPENSION
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
NA			a. Steer-Axle Tires
✓			b. All Other Tires
✓			c. Speed-Restricted Tires
			11. WHEELS AND RIMS
NA			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			12. WINDSHIELD GLAZING
NA			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
NA			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
NA			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, *proper size, proper placement (see 393.86).*
			16. OTHER
NA			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL

2241 (Rev. 1/22)