

ANNUAL VEHICLE INSPECTION REPORT

REPORT NUMBER	FLEET UNIT NUMBER
	11629
DATE 3-22-16	

MOTOR CARRIER OPERATOR <u>Bowman Leasing</u>		INSPECTOR'S NAME (PRINT OR TYPE) <u>Franklin Young</u>
ADDRESS <u>PO Box 433</u>		THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE <u>Williamsport MD 21795</u>		VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER <u>1NNVX5321XM300680</u>
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)		INSPECTION AGENCY/LOCATION (OPTIONAL)

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	✓			a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System				b. Protection against shifting cargo.	✓			b. All other tires.
✓			c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.	✓			a. Lock or Side Ring
✓			d. Brake Hose				a. Steering Wheel Free Play	✓			b. Wheels and Rims
✓			e. Brake Tubing				b. Steering Column	✓			c. Fasteners
✓			f. Low Pressure Warning Device				c. Front Axle Beam and All Steering Components Other Than Steering Column	✓			d. Welds
✓			g. Tractor Protection Valve				d. Steering Gear Box	✓			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
✓			h. Air Compressor				e. Pitman Arm	✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
✓			i. Electric Brakes				f. Power Steering	✓			List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes				g. Ball and Socket Joints				
✓			k. Vacuum Systems				h. Tie Rods and Drag Links				
✓			a. Fifth Wheels				i. Nuts				
✓			b. Pintle Hooks				j. Steering System				
✓			c. Drawbar/Towbar Eye				a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
✓			d. Drawbar/Towbar Tongue				b. Spring Assembly				
✓			e. Safety Devices				c. Torque, Radius or Tracking Components				
✓			f. Saddle-Mounts				a. Frame Members				
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.				b. Tire and Wheel Clearance				
✓			b. Bus exhaust system leaking or discharging in violation of standard.				c. Adjustable Axle Assemblies (Sliding Subframes)				
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.								
✓			a. Visible leak.								
✓			b. Fuel tank filler cap missing.								
✓			c. Fuel tank securely attached.								
✓			All lighting devices and reflectors required by Part 393 shall be operable.								

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.