

ANNUAL VEHICLE INSPECTION REPORT

REPORT NUMBER	FLEET UNIT NUMBER
	11931
DATE 2/15/16	

MOTOR CARRIER OPERATOR Bowman Sales & Equipment	INSPECTOR'S NAME (PRINT OR TYPE) James Williams
ADDRESS PO Box 433	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. YES
CITY, STATE, ZIP CODE Wilmington MD, 21795	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 1NNUX5329XM395434
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	NA			a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System	✓			b. Protection against shifting cargo.	✓			b. All other tires.
✓			c. Brake Drums or Rotors	✓			c. Container securement devices on intermodal equipment.	NA			a. Lock or Side Ring
✓			d. Brake Hose	✓			a. Steering Wheel Free Play	✓			b. Wheels and Rims
✓			e. Brake Tubing	✓			b. Steering Column	✓			c. Fasteners
NA			f. Low Pressure Warning Device	✓			c. Front Axle Beam and All Steering Components Other Than Steering Column	✓			d. Welds
✓			g. Tractor Protection Valve	NA			d. Steering Gear Box	NA			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
✓			h. Air Compressor	✓			e. Pitman Arm	NA			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
✓			i. Electric Brakes	✓			f. Power Steering	NA			List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes	✓			g. Ball and Socket Joints				
✓			k. Vacuum Systems	✓			h. Tie Rods and Drag Links				
NA			a. Fifth Wheels	✓			i. Nuts				
NA			b. Pintle Hooks	✓			j. Steering System				
NA			c. Drawbar/Towbar Eye	✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
NA			d. Drawbar/Towbar Tongue	✓			b. Spring Assembly				
NA			e. Safety Devices	✓			c. Torque, Radius or Tracking Components				
NA			f. Saddle-Mounts	✓			a. Frame Members				
NA			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓			b. Tire and Wheel Clearance				
NA			b. Bus exhaust system leaking or discharging in violation of standard.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
NA			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓							
NA			a. Visible leak.	✓							
NA			b. Fuel tank filler cap missing.	✓							
NA			c. Fuel tank securely attached.	✓							
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓							

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.