

RECORD OF ANNUAL INSPECTION

JS

INSPECTOR'S NAME Ed Bischoff TFL # 119534 DATE OF INSPECTION 11-24-15

MOTOR CARRIER NAME BS&E

ADDRESS PO Box 433 CITY Williamsport, Md STATE Md ZIP CODE 21795

VEHICLE IDENTIFICATION NUMBER VT006029 11407183 Tenn Hub0-129784

TYPE OF VEHICLE 8-99 Hyundai MODEL Van

VEHICLE COMPONENTS / RESULT OF INSPECTION

COMPONENT	PASS	FAIL	COMPONENT	PASS	FAIL	COMPONENT	PASS	FAIL	COMPONENT	PASS	FAIL
Brake Systems			Fuel System			Steering Mechanism			Tires		
Service Brakes	✓		Leaks			Steering Wheel Free Play			Treads	10/32	
Parking Brakes	✓		Caps			Steering Column			Labeled		
Brake Drums	✓		Bolts / Brackets			Front Axle Beam	✓		"Not for Highway Use"		
Brake Rotors	✓		Lighting System			Steering Components	✓		Markings		
Brake Hoses	✓		Headlights	✓		Gear Box			Mixed Tires on Same Axle	✓	
Brake Tubing	✓		Turn Signals	✓		Pitman Arm			Flaps	✓	
Low Pressure Warning Devices			Identification	✓		Power Steering			Regrooves	✓	
Tractor Protection Valve			Tail Lights	✓		Ball & Socket Joints			Repair Work		
Air Compressor			Stop Lights	✓		Tie Rods and Drag Links	✓		Excess Load Limits		
Electric Brakes			Clearance	✓		Nuts	✓		Contact with Vehicle		
Hydraulic Brakes			Reflectors	✓		Steering System	✓		Leaks		
Vacuum System			License Plate Lights (Rear)	✓		Suspension			Other		
Coupling Devices			Fifth Wheel	✓		U-Bolts	✓		Wheels & Rims		
Fifth Wheel			Hazard Warning	✓		Spring Hangers	✓		Lock or Side Ring	✓	
Pintle Hooks			Other			Axle Positioning Parts	✓		Wheels & Rims	✓	
Drawbar/Towbar Eye	✓		Safe Loading Systems			Spring Assembly	✓		Fasteners	✓	
Drawbar/Towbar Tongue			Parts	✓		Torque, Radius or Tracking	✓		Welds	✓	
Safety Devices			Condition	✓		Frame			Windshield Glazing		
Saddle Mounts			Protection Against Shifting Cargo	✓		Frame Members	✓		Cracks		
Exhaust System						Tire & Wheel Clearance	✓		Discoloration		
Leaks						Adjustable Axle Assemblies (Sliding Subframes)	✓		Vision Reducing Matter		
Location									Windshield Wipers		
									Inoperative		
									Missing or Damaged Parts		

Notes: _____

I certify the accuracy and completeness of this inspection. This inspection complies with all the requirements of 49CFR parts 396.17, 396.21 and Appendix G.

INSPECTOR'S SIGNATURE Ed Bischoff DATE 11-24-15