



VISUAL INSPECTION - PM/FEDERAL ANNUAL INSPECTION - TRAILER

Form conforms with FHWA 49CFR 396.17-396.23

Number: 08273

Inspecting Company: AL TUCKER TRAILERS

Inspecting Company's Address: Street 7401 N. LOOP E. City HOUSTON State TX

Trailer Number: 119617 (Shepard)

Make: Hyundai Year: 1999

Date: 12/31/15

Lic./Exp.: T429421 TW

Inspect each item and use these codes:

Serial Number: 3H3V532C4YT007017

Hub Reading: 027365

Codes: Needs Repair = X Serviced = S OK = ✓ Out of Service = O

Front

Inspect 7-Way Receptacle	✓
Inspect Glad Hands and Rubbers	✓
Inspect King Pin and Plate	✓
Inspect Clearance Lights	✓

Sides

Inspect Panels and Posts	✓
Inspect Marker Lights	✓
Inspect Bottom and Top Rails	✓
Inspect Conspicuity Tape	✓

Rear

Inspect Rear Impact Guard	✓
Inspect Mud Flaps and Brackets	✓
Inspect Rear Doors	✓
Inspect Door Holdbacks	✓

Suspension

Check Slider Operation	✓
Inspect Spring, Hangers, Saddles and U-Bolts	✓
Inspect Equalizers, Radius Rods and Bushings	✓

Brakes

Inspect Air Hoses	✓
Inspect Brake Drums	✓
Inspect Brake Linings	✓
Inspect Brake Chambers	✓
Check Valve Operation	✓
Lubricate Cams and Slack Adjusters	S
Adjust Brakes	S

Brake Pad Thickness in %

LF: 60 LR: 40 RF: 60 RR: 40

Tires

Inspect Rims and Lugnuts	✓
Inspect Tires for Irregular Wear	✓
Inflate Tires to 100 PSI	S
Tread Depth in 32nds	✓

lbs 122 LFO 13 32nds	lbs 122 LFI 5 32nds	lbs 122 LRO 14 32nds	lbs 122 LRI 10 32nds
lbs 122 RFO 9 32nds	lbs 122 RFI 14 32nds	lbs 122 RRO 14 32nds	lbs 122 RRI 14 32nds

Interior (if empty) Loaded At Dock

Inspect Walls for Damaged Linings	—
Inspect Scuff Liner and E-Trac	—
Inspect Roof and Roof Bows	—

General and Lubrication

Check for Registration and Tag	✓
Check Hub Oil Levels/Vents on Grease Caps	✓
Check Landing Gear Operation	✓
Inspect Sand Shoes/Axles/Braces	✓
Lubricate all Fittings	S
Lubricate Doors and Hinges	✓
Check Crossmembers	✓
Check Wheel Seals	✓

Comments: FHWA Sticker Updates: YES (✓) No ()

Your Signature: Warren Palmer

Print Name: Warren Palmer

Date: 12/31/15