

ANNUAL VEHICLE INSPECTION REPORT

REPORT NUMBER		FLEET UNIT NUMBER 119980	
DATE 3/16/16			
MOTOR CARRIER OPERATOR Bowman Sales & Equipment		INSPECTOR'S NAME (PRINT OR TYPE) James Williams	
ADDRESS PO Box 433		THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES	
CITY, STATE, ZIP CODE Williamsport Md 21795		VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER	
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)		1GRAA062785023422 INSPECTION AGENCY/LOCATION (OPTIONAL)	

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			a. Service Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	NA			a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System	✓			b. Protection against shifting cargo.	✓			b. All other tires.
✓			c. Brake Drums or Rotors	✓			c. Container securement devices on intermodal equipment.	✓			a. Lock or Side Ring
✓			d. Brake Hose	✓				✓			b. Wheels and Rims
✓			e. Brake Tubing	✓				✓			c. Fasteners
NA			f. Low Pressure Warning Device	NA				✓			d. Welds
✓			g. Tractor Protection Valve	✓				NA			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
✓			h. Air Compressor	✓				✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
✓			i. Electric Brakes	✓				NA			List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes	✓							
✓			k. Vacuum Systems	✓							
✓			a. Fifth Wheels	✓			a. Steering Wheel Free Play				
✓			b. Pintle Hooks	✓			b. Steering Column				
✓			c. Drawbar/Towbar Eye	✓			c. Front Axle Beam and All Steering Components Other Than Steering Column				
✓			d. Drawbar/Towbar Tongue	✓			d. Steering Gear Box				
✓			e. Safety Devices	✓			e. Pitman Arm				
✓			f. Saddle-Mounts	✓			f. Power Steering				
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓			g. Ball and Socket Joints				
✓			b. Bus exhaust system leaking or discharging in violation of standard.	✓			h. Tie Rods and Drag Links				
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			i. Nuts				
✓				✓			j. Steering System				
✓				✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
✓				✓			b. Spring Assembly				
✓				✓			c. Torque, Radius or Tracking Components				
✓			a. Visible leak.	✓			a. Frame Members				
✓			b. Fuel tank filler cap missing.	✓			b. Tire and Wheel Clearance				
✓			c. Fuel tank securely attached.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓							

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK ☒ NEEDS REPAIR ☒ IF ITEMS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.