

Annual Vehicle Inspection Report

Bill's Tire & Trailer Service

730 Randall Rd, PO BOX 458

Ludlow, MA 01056

Vehicle History Record	
Report Number	Field Unit Number
	120824
Date	3-17-15

Motor Carrier Operator <i>Bonnie Leasing</i>	Inspector's Name <i>Paul Rae</i>
Address <i>4401 W 62ND ST</i>	This Inspector Meets the qualification requirements in section 396.19 ☒ Yes
City, State, Zip Code <i>Indianapolis IN 46260</i>	Vehicle ID # and complete <i>X</i> Lic. Plate # <i>X</i> VIN <i>X</i> Other
Vehicle Type ☐ Tractor ☒ Trailer ☐ Truck ☐ Other	Inspection Agency/ID# <i>PA49852 MD-120824</i>

Vehicle Components Inspected

OK	Repair Date	Item	OK	Repair Date	Item	OK	Repair Date	Item
☒		1. Brake System	☒		4. Fuel System	☒		7. Frame Members
☒		a. Service Brakes	☒		a. Visible leak	☒		b. Tire & Wheel Clearance
☒		b. Parking Brake System	☒		b. Fuel Tank filler cap missing	☒		c. Adjustable Axle Assemblies
☒		c. Brake Drums or Rotors	☒		c. Fuel tank securely attached	☒		
☒		d. Brake Hose	☒		5. Lighting Devices	☒		b. Non Steer Tires
☒		e. Brake Tubing	☒		All Lighting devices and reflectors required by Section 393 shall be operable	☒		b. Tires on any steering axle of a power unit
☒		f. Low Pressure Warning Device	☒		6. Safe Loading	☒		a. Lock or Side Ring
☒		g. Tractor Protection Valve	☒		a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	☒		b. Wheels & Rims
☒		h. Air Compressor	☒		b. Protection against shifting cargo.	☒		c. Fasteners
☒		i. Electric Brakes	☒		7. Steering Mechanism	☒		d. Welds
☒		j. Hydraulic Brakes	☒		a. Steering Wheel Free Play	☒		Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (ref. 393.60 for exceptions)
☒		k. Vacuum system	☒		b. Steering Column	☒		Any power Unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
☒		2. Coupling Devices	☒		c. Front axle Beam and all steering components other than steering column	☒		
☒		a. Fifth Wheel	☒		d. Steering Gear Box	☒		
☒		b. Pintle Hooks	☒		e. Pitman Arm	☒		
☒		c. Drawbar/Towbar Eye	☒		f. Power Steering	☒		
☒		d. Drawbar/Towbar Tongue	☒		g. Ball and Socket Joints	☒		
☒		e. Safety Devices	☒		h. Tie Rods and Drag Links	☒		
☒		f. Saddle Mounts	☒		i. Nuts	☒		
☒		3. Exhaust System	☒		j. Steering System	☒		
☒		a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment	☒		8. Suspension	☒		
☒		b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3)	☒		a. Any U-bolts, spring hangers, or other axle positioning parts broken, loose, or missing resulting in shifting of an axle from its normal position.	☒		
☒		c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply or any combustible part of the motor vehicle.	☒		b. Spring Assembly	☒		
☒			☒		c. Torque, Radius, Tracking Components	☒		

NF

CERTIFICATION: This Vehicle has passed all the inspection items for the Annual Vehicle Inspection Report in Accordance with 49 CFR 396.