

Annual Vehicle Inspection Report

Vehicle History Record	
Report Number	120426
Fleet Unit Number	120426
Date	5-21-15

Inspector's Name	Billie Rae
This Inspector Meet the qualification requirements in section 396.19	Yes
City, State, Zip Code	Indianapolis, IN 46208
Vehicle ID # and complete	120426
Lic. Plate #	120426
Other	120426
Vehicle Type	Tractor Trailer

Vehicle Components Inspected

Item	OK	Needs Repair	Item	OK	Needs Repair	Item	OK	Needs Repair
1. Brake System			4. Fuel System			9. Frame		
a. Service Brakes			a. Visible leak			a. Frame Members		
b. Parking Brake System			b. Fuel Tank filler cap missing			b. Tire & Wheel Clearance		
c. Brake Drums or Rotors			c. Fuel tank securely attached			c. Adjustable Axle Assemblies		
d. Brake Hose								
e. Brake Tubing								
f. Low Pressure Warning Device								
g. Tractor Protection Valve								
h. Air Compressor								
i. Electric Brakes								
j. Hydraulic Brakes								
k. Vacuum system								
2. Coupling Devices			6. Safe Loading			11. Wheels & Rims		
a. Fifth Wheel			a. Part(s) of vehicle or the spare tire or any part of condition of loading such that			a. Lock or Side Ring		
b. Pintle Hooks			b. Protection against shifting cargo.			b. Wheels & Rims		
c. Drawbar/Towbar Eye						c. Fasteners		
d. Drawbar/Towbar Tongue						d. Welds		
e. Safety Devices								
f. Saddle Mounts			7. Steering Mechanism					
a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment			a. Steering Wheel Free Play					
b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3)			b. Steering Column					
c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply or any combustible part of the motor vehicle.			c. Front axle Beam and all steering components other than steering column					
			d. Steering Gear Box					
			e. Pitman Arm					
			f. Power Steering					
			g. Ball and Socket Joints					
			h. Tie Rods and Drag Links					
			i. Nuts					
			j. Steering System					
			8. Suspension					
			a. Any U-bolts, spring hangers, or other axle positioning parts broken, loose, or missing resulting in shifting of an axle from its normal position.					
			b. Spring Assembly					
			c. Torque, Radius, Tracking Components					

CERTIFICATION: This Vehicle has passed all the inspection items for the Annual Vehicle Inspection Report in Accordance with 49 CFR 396.