

(FHWA) INSPECTION REPORT

Chassis No: FRL2123230 License #: 20R40311 Expires: 2/29/20 State: MAINE

Owner Designated by Chassis Mark: Bowman Location Inspection Performed: Glover Trailers Leasing

VIN No. 1S13SC307B735389

COMPONENT	O.K.	DEFECT	DEFECTIVE ITEM REPAIRED/REPLACED
LIGHTS	✓		
REFLECTORS	✓		
WIRING	✓		
BRAKES	✓		
AIRLINE & TUBES	✓		
KINGPIN	✓		
TIRES	✓		
WHEELS & RIMS	✓		
FRAME ASSEMBLY	✓		
SUSPENSION	✓		

RIC	Fire Stone	12	100		LIC	West lake	10	100	
ROC	Road master	6	100		Tire Condition	West lake	12	100	
					LOC				
Position	Brand	Tread	Air	Remarks	Position	Brand	Tread	Air	Remarks
RIF	West lake	9	100		LIF	West lake	10	100	
ROF	Good Year	9	100		LOF	West lake	12	100	
RIR	West lake	100	11		LIR	West lake	9	100	
ROR	West lake	100	12		LOR	West lake	8	100	

*The electronic signature below acknowledges that this unit has been accurately and completely inspected on the date below and any defective item repaired or replaced as required by 49 CFR 396.17 & 396.21

* This form must be electronically sent on a daily basis.

Inspector's name: <u>[Signature]</u>	Date: <u>17 Mar 16</u>
Vendor performing inspection & Inspector's signature: <u>[Signature]</u>	