

BOWMAN

REPORT NUMBER	FLEET UNIT NUMBER
DATE	127473

TOP CARRIER OPERATOR

ADDRESS

ZIP CODE

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE
1. BRAKE SYSTEM				6. SAFE LOADING			
a. Service Brakes	✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	✓		
b. Parking Brake System	✓			b. Protection against shifting cargo.	✓		
c. Brake Drums or Rotors	✓			c. Container securement devices on intermodal equipment.	✓		
d. Brake Hose	✓			7. STEERING MECHANISM			
e. Brake Tubing	✓			a. Steering Wheel Free Play	NA		
f. Low Pressure Warning Device	✓			b. Steering Column	NA		
g. Tractor Protection Valve	✓			c. Front Axle Beam and All Steering Components Other Than Steering Column	NA		
h. Air Compressor	✓			d. Steering Gear Box	NA		
i. Electric Brakes	✓			e. Pitman Arm	NA		
j. Hydraulic Brakes	✓			f. Power Steering	NA		
k. Vacuum Systems	✓			g. Ball and Socket Joints	NA		
2. COUPLING DEVICES				h. Tie Rods and Drag Links	NA		
a. Fifth Wheels	✓			i. Nuts	NA		
b. Pintle Hooks	✓			j. Steering System	NA		
c. Drawbar/Towbar Eye	✓			8. SUSPENSION			
d. Drawbar/Towbar Tongue	✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	✓		
e. Safety Devices	✓			b. Spring Assembly	✓		
f. Saddle-Mounts	✓			c. Torque, Radius or Tracking Components	✓		
3. EXHAUST SYSTEM				9. FRAME			
a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓			a. Frame Members	✓		
b. Bus exhaust system leaking or discharging in violation of standard.	✓			b. Tire and Wheel Clearance	✓		
c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)	✓		
4. FUEL SYSTEM				10. TIRES			
a. Visible leak.	✓			a. Tires on any steering axle of a power unit.	✓		
b. Fuel tank filler cap missing.	✓			b. All other tires.	✓		
c. Fuel tank securely attached.	✓			11. WHEELS AND RIMS			
5. LIGHTING DEVICES				a. Lock or Side Ring	✓		
All lighting devices and reflectors required by Part 393 shall be operable.	✓			b. Wheels and Rims	✓		
				c. Fasteners	✓		
				d. Welds	✓		
				12. WINDSHIELD GLAZING			
				Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).			
				13. WINDSHIELD WIPERS			
				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.			
				14. OTHER			
				List any other condition(s) which may prevent safe operation of this vehicle.			

NOTES: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

STATEMENT: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

INSPECTOR: KELLER & ASSOCIATES, INC.®
 (800) 327-6868
 Inspected in the United States

ORIGINAL

2241
 (Rev. 11/12)