ANNUAL VEHICLE INSPECTION REPORT

REPORT NUMBER	FLEET UNIT NUMBER
	345780

DATE 11/17/15

MOTOR CARRIER OPERATOR: Bowman Sales and Equipment

ADDRESS: PO Box 433

CITY, STATE, ZIP CODE: Williamsport Md. 21795

VEHICLE TYPE: ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE): James Williams

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER: 1JJV532W37L047195

INSPECTION AGENCY/LOCATION (OPTIONAL)

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
N/A			f. Low Pressure Warning Device
			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
✓			a. Fifth Wheels
N/A			b. Pintle Hooks
			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
			e. Safety Devices
			f. Saddle-Mounts
N/A			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.
			b. Bus exhaust system leaking or discharging in violation of standard.
			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.
N/A			a. Visible leak.
			b. Fuel tank filler cap missing.
✓			c. Fuel tank securely attached.
✓			All lighting devices and reflectors required by Part 393 shall be operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.
✓			b. Protection against shifting cargo.
N/A			c. Container securement devices on intermodal equipment.
N/A			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam and All Steering Components Other Than Steering Column
			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
✓			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
N/A			a. Tires on any steering axle of a power unit.
✓			b. All other tires.
N/A			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
			d. Welds
N/A			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
N/A			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.

List any other condition(s) which may prevent safe operation of this vehicle.

Hubs
14877D

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, N/A IF ITEMS DO NOT APPLY. ____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

© Copyright 2012 J. J. KELLER & ASSOCIATES, INC.®
Neenah, WI • USA • (800) 327-6868
jjkeller.com • Printed in the United States

ORIGINAL